

Distillation Troubleshooting


Henry Z. Kister

Fluor Corporation






A JOHN WILEY & SONS, INC., PUBLICATION



Distillation Troubleshooting



Distillation Troubleshooting

Henry Z. Kister

Fluor Corporation

AIChE®



A JOHN WILEY & SONS, INC., PUBLICATION

DISCLAIMER

The author and contributors to "Distillation Troubleshooting" do not represent, warrant, or otherwise guarantee, expressly or impliedly, that following the ideas, information, and recommendations outlined in this book will improve tower design, operation, downtime, troubleshooting, or the suitability, accuracy, reliability or completeness of the information or case histories contained herein. The users of the ideas, the information, and the recommendations contained in this book apply them at their own election and at their own risk. The author and the contributors to this book each expressly disclaims liability for any loss, damage or injury suffered or incurred as a result of or related to anyone using or relying on any of the ideas or recommendations in this book. The information and recommended practices included in this book are not intended to replace individual company standards or sound judgment in any circumstances. The information and recommendations in this book are offered as lessons from the past to be considered for the development of individual company standards and procedures.

Copyright © 2006 by John Wiley & Sons, Inc. All rights reserved.

Published by John Wiley & Sons, Inc., Hoboken, New Jersey. Published simultaneously in Canada.

No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, scanning, or otherwise, except as permitted under Section 107 or 108 of the 1976 United States Copyright Act, without either the prior written permission of the Publisher, or authorization through payment of the appropriate per-copy fee to the Copyright Clearance Center, Inc., 222 Rosewood Drive, Danvers, MA 01923, 978-750-8400, fax 978-646-8600, or on the web at www.copyright.com. Requests to the Publisher for permission should be addressed to the Permissions Department, John Wiley & Sons, Inc., 111 River Street, Hoboken, NJ 07030, (201) 748-6011, fax (201) 748-6008, or online at www.wiley.com/go/permission.

Limit of Liability/Disclaimer of Warranty: While the publisher and author have used their best efforts in preparing this book, they make no representations or warranties with respect to the accuracy or completeness of the contents of this book and specifically disclaim any implied warranties of merchantability or fitness for a particular purpose. No warranty may be created or extended by sales representatives or written sales materials. The advice and strategies contained herein may not be suitable for your situation. You should consult with a professional where appropriate. Neither the publisher nor author shall be liable for any loss of profit or any other commercial damages, including but not limited to special, incidental, consequential, or other damages.

For general information on our other products and services please contact our Customer Care Department within the U.S. at 800-762-2974, outside the U.S. at 317-572-3993 or fax 317-572-4002.

Wiley also publishes its books in a variety of electronic formats. Some content that appears in print, may not be available in electronic format. For more information about Wiley products, visit out web site at www.wiley.com.

2004016490

Library of Congress Cataloging-in-Publication Data:

```
Kister, Henry Z.

Distillation troubleshooting / Henry Z. Kister.
p. cm.
Includes bibliographical references.
ISBN-13 978-0-0471-46744-1 (Cloth)
ISBN-10 0-471-46744-8 (Cloth)
1. Distillation apparatus—Maintenance and repair. I. Title.
TP159.D9K57 2005
```


Printed in the United States of America

10 9 8 7 6 5

660'.28425--dc22

To my son, Abraham and my wife, Susana, who have been my love, inspiration, and the lighthouses illuminating my path,

and to my life-long mentor, Dr. Walter Stupin – it is easy to rise when carried on the shoulders of giants.



Contents

Preface xxiii	
Acknowledgments xxvii	
How to Use this Book xxix	
Abbreviations xxxi	
1. Troubleshooting Distillation Simulations	1
2. Where Fractionation Goes Wrong	25
3. Energy Savings and Thermal Effects	61
4. Tower Sizing and Material Selection Affect Performance	73
5. Feed Entry Pitfalls in Tray Towers	97
6. Packed-Tower Liquid Distributors: Number 6 on the Top 10 Malfunctions	111
7. Vapor Maldistribution in Trays and Packings	133
8. Tower Base Level and Reboiler Return: Number 2 on the Top 10 Malfunctions	145
9. Chimney Tray Malfunctions: Part of Number 7 on the Top 10 Malfunctions	163
10. Draw-Off Malfunctions (Non-Chimney Tray) Part of Number 7 on the Top 10 Malfunctions	179

<u> 11.</u>	Tower Assembly Mishaps: Number 5 on the Top 10 Malfunctions	193
12.	Difficulties During Start-Up, Shutdown, Commissioning, and Abnormal Operation: Number 4 on the Top 10 Malfunctions	215
13.	Water-Induced Pressure Surges: Part of Number 3 on the Top 10 Malfunctions	225
14.	Explosions, Fires, and Chemical Releases: Number 10 on the Top 10 Malfunctions	233
15.	Undesired Reactions in Towers	237
16.	Foaming	241
17.	The Tower as a Filter: Part A. Causes of Plugging—Number 1 on the Top 10 Malfunctions	253
18.	The Tower as a Filter: Part B. Location of Plugging—Number 1 on the Top 10 Malfunctions	257
19.	Coking: Number 1 on the Top 10 Malfunctions	271
20.	Leaks	281
21.	Relief and Failure	287
22.	Tray, Packing, and Tower Damage: Part of Number 3 on the Top 10 Malfunctions	291
23.	Reboilers That Did Not Work: Number 9 on the Top 10 Malfunctions	315
24.	Condensers That Did Not Work	335
25.	Misleading Measurements: Number 8 on the Top 10 Malfunctions	347

		Contents	İX
26. Co	ontrol S	ystem Assembly Difficulties	357
27. W	here Do	Temperature and Composition Controls Go Wrong?	373
28. M	isbehav	ed Pressure, Condenser, Reboiler, and Preheater Controls	377
29. M	iscellan	eous Control Problems	395
		ISTILLATION TROUBLESHOOTING DATABASE OF PUBLISHED CASE HISTORIES	
1. Tro	ublesho	ooting Distillation Simulations	398
1.1	VLE	398	
	1.1.1	Close-Boiling Systems 398	
	1.1.2	Nonideal Systems 399	
	1.1.3	Nonideality Predicted in Ideal System 400	
	1.1.4		
	1.1.5	Nonideal VLE Extrapolated to Different Pressures 401	
	1.1.6	Incorrect Accounting for Association Gives	
		Wild Predictions 401	
	1.1.7	Poor Characterization of Petroleum Fractions 402	
		istry, Process Sequence 402	
1.3	Does	Your Distillation Simulation Reflect the Real World? 404	
		General 404	
		With Second Liquid Phase 406	
	1.3.3		
	1.3.4		
	1.3.5	Simulation/Plant Data Mismatch Can Be Due to an	
	100	Unexpected Internal Leak 406	
	1.3.6	Simulation/Plant Data Mismatch Can Be Due to	
	1 2 7	Liquid Entrainment in Vapor Draw 407	
1.4	1.3.7	Bug in Simulation 407	
1.4	1.4.1	ical Techniques to Troubleshoot Simulations 407	
	1.4.1	McCabe—Thiele and Hengstebeck Diagrams 407 Multicomponent Composition Profiles 407	
1.5	1.4.3	Residue Curve Maps 407 Good Is Your Efficiency Estimate? 407	
1.5		ator Hydraulic Predictions: To Trust or Not to Trust 409	
1.0	1.6.1	Do Your Vapor and Liquid Loadings Correctly	
	1.0.1	Reflect Subcool, Superheat, and Pumparounds? 409	
	1.6.2	How Good Are the Simulation Hydraulic	
	1.0.2	Prediction Correlations? 409	

<u>z.</u>	vv ne	ere Fractionation Goes Wrong	410
	2.1	Insufficient Reflux or Stages; Pinches 410	
	2.2	No Stripping in Stripper 412	
	2.3	Unique Features of Multicomponent Distillation 412	
	2.4	Accumulation and Hiccups 413	
		2.4.1 Intermediate Component, No Hiccups 413	
		2.4.2 Intermediate Component, with Hiccups 414	
		2.4.3 Lights Accumulation 416	
		2.4.4 Accumulation between Feed and Top	
		or Feed and Bottom 417	
		2.4.5 Accumulation by Recycling 418	
		2.4.6 Hydrates, Freeze–Ups 418	
	2.5	Two Liquid Phases 419	
	2.6	Azeotropic and Extractive Distillation 421	
		2.6.1 Problems Unique to Azeotroping 421	
		2.6.2 Problems Unique to Extractive Distillation 423	
2	Enc	ngy Cavings and Thormal Effects	424
5.	Lile	rgy Savings and Thermal Effects	424
	3.1	Energy-Saving Designs and Operation 424	
		3.1.1 Excess Preheat and Precool 424	
		3.1.2 Side-Reboiler Problems 424	
		3.1.3 Bypassing a Feed around the Tower 424	
		3.1.4 Reducing Recycle 425	
		3.1.5 Heat Integration Imbalances 426	
	3.2	Subcooling: How It Impacts Towers 428	
		3.2.1 Additional Internal Condensation and Reflux 428	
		3.2.2 Less Loadings above Feed 429	
		3.2.3 Trapping Lights and Quenching 429	
		3.2.4 Others 430	
	3.3	Superheat: How It Impacts Towers 430	
4.	Tow	er Sizing and Material Selection Affect Performance	431
	4.1	Undersizing Trays and Downcomers 431	_
	4.2	Oversizing Trays 431	
	4.3	Tray Details Can Bottleneck Towers 433	
	4.4	Low Liquid Loads Can Be Troublesome 434	
		4.4.1 Loss of Downcomer Seal 434	
		4.4.2 Tray Dryout 435	
	4.5	Special Bubble-Cap Tray Problems 436	
	4.6	Misting 437	
	4.7	Undersizing Packings 437	
	4.8	Systems Where Packings Perform Different from Expectations	437

	4.9	Packed Bed 100 Long 438	
	4.10	Packing Supports Can Bottleneck Towers 439	
	4.11	Packing Hold-downs Are Sometimes Troublesome 440	
	4.12	Internals Unique to Packed Towers 440	
	4.13	Empty (Spray) Sections 440	
5.	Feed	Entry Pitfalls in Tray Towers	441
	5.1	Does the Feed Enter the Correct Tray? 441	
	5.2	Feed Pipes Obstructing Downcomer Entrance 441	
	5.3	Feed Flash Can Choke Downcomers 441	
	5.4	Subcooled Feeds, Refluxes Are Not Always Trouble Free 442	
	5.5	Liquid and Unsuitable Distributors Do Not Work	
		with Flashing Feeds 442	
	5.6	Flashing Feeds Require More Space 443	
	5.7	Uneven or Restrictive Liquid Split to Multipass Trays	
		at Feeds and Pass Transitions 443	
	5.8	Oversized Feed Pipes 444	
	5.9	Plugged Distributor Holes 444	
	5.10	Low ΔP Trays Require Decent Distribution 445	
	Dools	ad Tawan Liquid Distributores Number 6 on the	
v.		ed-Tower Liquid Distributors: Number 6 on the	440
_	Tob 1	o manuncuons	441
	6.1	Better Quality Distributors Improve Performance 446	
		6.1.1 Original Distributor Orifice or Unspecified 446	
		6.1.2 Original Distributor Weir Type 447	
		6.1.3 Original Distributor Spray Type 447	
	6.2	Plugged Distributors Do Not Distribute Well 448	
		6.2.1 Pan/Trough Orifice Distributors 448	
		6.2.2 Pipe Orifice Distributors 449	
		6.2.3 Spray Distributors 450	
	6.3	Overflow in Gravity Distributors: Death to Distribution 451	
	6.4	Feed Pipe Entry and Predistributor Problems 454	
	6.5	Poor Flashing Feed Entry Bottleneck Towers 455	
	6.6	Oversized Weep Holes Generate Undesirable Distribution 456	
	6.7	Damaged Distributors Do Not Distribute Well 457	
		6.7.1 Broken Flanges or Missing Spray Nozzles 457	
		6.7.2 Others 457	
	6.8	Hole Pattern and Liquid Heads Determine Irrigation Quality 458	
	6.9	Gravity Distributors Are Meant to Be Level 459	
	6.10	Hold-Down Can Interfere with Distribution 460	
	6.11	Liquid Mixing Is Needed in Large-Diameter Distributors 460	
	6.12	Notched Distributors Have Unique Problems 461	
	6.13	Others 461	

7.	Vap	or Maldistribution in Trays and Packings	462
	7.1	Vapor Feed/Reboiler Return Maldistributes Vapor	
		to Packing Above 462	
		7.1.1 Chemical/Gas Plant Packed Towers 462	
		7.1.2 Packed Refinery Main Fractionators 463	
	7.2		
	7.3		
		and Chimney Trays 465	
	7.4	Vapor Maldistribution Is Detrimental in Tray Towers 466	
		7.4.1 Vapor Cross-Flow Channeling 466	
		7.4.2 Multipass Trays 467	
		7.4.3 Others 467	
8.	Tow	er Base Level and Reboiler Return: Number 2 on the	
	Top	10 Malfunctions	468
	8.1	Causes of High Base Level 468	
		8.1.1 Faulty Level Measurement or Level Control 468	
		8.1.2 Operation 469	
		8.1.3 Excess Reboiler Pressure Drop 470	
		8.1.4 Undersized Bottom Draw Nozzle or Bottom Line 470	
		8.1.5 Others 470	
	8.2	High Base Level Causes Premature Tower Flood	
		(No Tray/Packing Damage) 470	
	8.3	High Base Liquid Level Causes Tray/Packing Damage 471	
	8.4	Impingement by the Reboiler Return Inlet 472	
		8.4.1 On Liquid Level 472	
		8.4.2 On Instruments 473	
		8.4.3 On Tower Wall 473	
		8.4.4 Opposing Reboiler Return Lines 474	
		8.4.5 On Trays 474	
	0.5	8.4.6 On Seal Pan Overflow 474	
	8.5		
	8.7	Low Base Liquid Level 475 Issues with Tower Base Baffles 476	
	8.8	Vortexing 476	
	0.0	To the same of the	
9.		mney Tray Malfunctions: Part of Number 7 on the 10 Malfunctions	477
_			477
	9.1	Leakage 477	
	9.2	Problem with Liquid Removal, Downcomers, or Overflows 478	
	9.3	Thermal Expansion Causing Warping, Out-of-Levelness 479	
	9.4	Chimneys Impeding Liquid Flow to Outlet 480	

		Vapor from Chimneys Interfering with Incoming Liquid 480	
		evel Measurement Problems 481	
	9.7	Coking, Fouling, Freezing 482	
	9.8	Other Chimney Tray Issues 482	
10.		yoff Malfunctions (Non–Chimney Tray): Part of Number 7 on op 10 Malfunctions	484
	10.1	Vapor Chokes Liquid Draw Lines 484	
		10.1.1 Insufficient Degassing 484	
		10.1.2 Excess Line Pressure Drop 485	
		10.1.3 Vortexing 486	
	10.2	Leak at Draw Tray Starves Draw 486	
	10.3	Draw Pans and Draw Lines Plug Up 488	
	10.4	Draw Tray Damage Affects Draw Rates 488	
	10.5	Undersized Side-Stripper Overhead Lines Restrict Draw Rates	488
	10.6	Degassed Draw Pan Liquid Initiates Downcomer Backup Flood	489
	10.7	Other Problems with Tower Liquid Draws 489	
	10.8	Liquid Entrainment in Vapor Side Draws 490	
	10.9	Reflux Drum Malfunctions 490	
		10.9.1 Reflux Drum Level Problems 490	
		10.9.2 Undersized or Plugged Product Lines 490	
		10.9.3 Two Liquid Phases 490	
11.	Towe	er Assembly Mishaps: Number 5 on the Top 10 Malfunctions	491
	11.1	Incorrect Tray Assembly 491	
	11.2	Downcomer Clearance and Inlet Weir Malinstallation 491	
	11.3	Flow Passage Obstruction and Internals Misorientation	
		at Tray Tower Feeds and Draws 492	
	11.4	Leaking Trays and Accumulator Trays 493	
	11.5	Bolts, Nuts, Clamps 493	
	11.6	Manways/Hatchways Left Unbolted 493	
	11.7	Materials of Construction Inferior to Those Specified 494	
	11.8	Debris Left in Tower or Piping 494	
	11.9	Packing Assembly Mishaps 495	
		11.9.1 Random 495	
		11.9.2 Structured 496	
		11.9.3 Grid 496	
	11.10		496
	11.11		
	11.12		498
	11.13	• • • • • • • • • • • • • • • • • • • •	

12.		mal Operation: Number 4 on the Top 10 Malfunctions	499
	12.1	Blinding/Unblinding Lines 499	
	12.2	Backflow 500	
	12.3	Dead-Pocket Accumulation and Release of Trapped Materials	501
	12.4	Purging 501	
	12.5	Pressuring and Depressuring 502	
	12.6	Washing 502	
	12.7	On-Line Washes 504	
	12.8	Steam and Water Operations 506	
	12.9	Overheating 506	
	12.10	Cooling 507	
	12.11	Overchilling 507	
	12.12	Water Removal 508	
		12.12.1 Draining at Low Points 508	
		12.12.2 Oil Circulation 508	
		12.12.3 Condensation of Steam Purges 508	
		12.12.4 Dehydration by Other Procedures 508	
	12.13	Start-Up and Initial Operation 509	
		12.13.1 Total-Reflux Operation 509	
		12.13.2 Adding Components That Smooth Start-Up 509	
		12.13.3 Siphoning 509	
		12.13.4 Pressure Control at Start-Up 510	
	12.14	Confined Space and Manhole Hazards 510	
12	XX 7-4	Taland David Co. D. 4 CN. J. 2 4	
13.		-Induced Pressure Surges: Part of Number 3 on the Malfunctions	512
	13.1	Water in Feed and Slop 512	
	13.2	Accumulated Water in Transfer Line to Tower and in	
	10.0	Heater Passes 513	
	13.3	Water Accumulation in Dead Pockets 513	
	13.4	Water Pockets in Pump or Spare Pump Lines 514	
	13.5	Undrained Stripping Steam Lines 515	
	13.6	Condensed Steam or Refluxed Water Reaching Hot Section	516
	13.7	Oil Entering Water-Filled Region 517	
14.	Explos	sions, Fires, and Chemical Releases: Number 10 on the	
		0 Malfunctions	518
	14.1	Explosions Due to Decomposition Reactions 518	
		14.1.1 Ethylene Oxide Towers 518	
		14.1.2 Peroxide Towers 519	
		14.1.3 Nitro Compound Towers 520	
		14.1.4 Other Unstable-Chemical Towers 521	

	14.2	Explosions Due to Violent Reactions 523
	14.3	Explosions and Fires Due to Line Fracture 524
	14.5	14.3.1 C ₃ -C ₄ Hydrocarbons 524
		14.3.2 Overchilling 525
		14.3.3 Water Freeze 526
		14.3.4 Other 527
	14.4	Explosions Due to Trapped Hydrocarbon or Chemical Release 527
	14.5	Explosions Induced by Commissioning Operations 528
	14.6	Packing Fires 529
		14.6.1 Initiated by Hot Work Above Steel Packing 529
		14.6.2 Pyrophoric Deposits Played a Major Role, Steel Packing 530
		14.6.3 Tower Manholes Opened While Packing Hot,
		Steel Packing 532
		14.6.4 Others, Steel Packing Fires 532
		14.6.5 Titanium, Zinconium Packing Fires 533
	14.7	Fires Due to Opening Tower before Cooling
		or Combustible Removal 533
	14.8	Fires Caused by Backflow 534
	14.9	Fires by Other Causes 535
	14.10	Chemical Releases by Backflow 536
	14.11	Trapped Chemicals Released 536
	14.12	Relief, Venting, Draining, Blowdown to Atmosphere 537
15.	Undesi	red Reactions in Towers 539
	15.1	Excessive Bottom Temperature/Pressure 539
	15.2	Hot Spots 539
	15.3	Concentration or Entry of Reactive Chemical 539
	15.4	Chemicals from Commissioning 540
	15.5	Catalyst Fines, Rust, Tower Materials Promote Reaction 540
	15.6	Long Residence Times 541
	15.7	Inhibitor Problems 541
	15.8	Air Leaks Promote Tower Reactions 542
	15.9	Impurity in Product Causes Reaction Downstream 542
16.	Foami	ng 543
	16.1	What Causes or Promotes Foaming? 543
	16.1	What Causes or Promotes Foaming? 543 16.1.1 Solids, Corrosion Products 543
	16.1	
	16.1	16.1.1 Solids, Corrosion Products 543
	16.1	 16.1.1 Solids, Corrosion Products 543 16.1.2 Corrosion and Fouling Inhibitors, Additives, and Impurities 544 16.1.3 Hydrocarbon Condensation into Aqueous Solutions 545
	16.1	 16.1.1 Solids, Corrosion Products 543 16.1.2 Corrosion and Fouling Inhibitors, Additives, and Impurities 544
	16.1	 16.1.1 Solids, Corrosion Products 543 16.1.2 Corrosion and Fouling Inhibitors, Additives, and Impurities 544 16.1.3 Hydrocarbon Condensation into Aqueous Solutions 545

	16.2	What A	Are Foams Sensitive To? 546	
		16.2.1	Feedstock 546	
		16.2.2	Temperature 547	
		16.2.3	Pressure 547	
	16.3	Laborat	ory Tests 547	
		16.3.1	Sample Shake, Air Bubbling 547	
		16.3.2	Oldershaw Column 547	
		16.3.3	Foam Test Apparatus 548	
			At Plant Conditions 548	
	16.4	Antifoa	m Injection 548	
		16.4.1	Effective Only at the Correct Quantity/Concentration 548	
			Some Antifoams Are More Effective Than Others 549	
		16.4.3	Batch Injection Often Works, But Continuous	
			Can Be Better 549	
		16.4.4	Correct Dispersal Is Important, Too 550	
		16.4.5	Antifoam Is Sometimes Adsorbed on Carbon Beds 550	
		16.4.6	Other Successful Antifoam Experiences 550	
			Sometimes Antifoam Is Less Effective 551	
	16.5	System	Cleanup Mitigates Foaming 551	
		16.5.1	Improving Filtration 551	
		16.5.2	Carbon Beds Mitigate Foaming But Can	
			Adsorb Antifoam 553	
		16.5.3	Removing Hydrocarbons from Aqueous Solvents 553	
		16.5.4	Changing Absorber Solvent 553	
		16.5.5	Other Contaminant Removal Techniques 554	
	16.6	Hardwa	re Changes Can Debottleneck Foaming Towers 555	
		16.6.1	Larger Downcomers 555	
		16.6.2	Smaller Downcomer Backup (Lower Pressure Drop,	
			Larger Clearances) 556	
		16.6.3	More Tray Spacing 556	
		16.6.4	Removing Top Two Trays Does Not Help 556	
		16.6.5	Trays Versus Packings 556	
		16.6.6	Larger Packings, High-Open-Area Distributors Help 557	
		16.6.7	•	
		16.6.8	Larger Tower 557	
		16.6.9	Reducing Base Level 557	
17.	The T	lower as	a Filter: Part A. Causes of Plugging—Number 1	
				58
				_
	17.1		Scale/Corrosion Products 558	
	17.2	-	Out/Precipitation 559	
	17.3		r/Reaction Products 560	
	17.4		Entrainment in the Feed 561	
	17.5	Oil Lea	k 561	

	17.6	Poor Shutdown Wash/Flush 562	
	17.7	Entrainment or Drying at Low Liquid Rates 562	
	17.8	Others 562	
18.		Tower as a Filter: Part B. Locations of Plugging—Number 1	
	on the	e Top 10 Malfunctions	563
	18.1	Trays 563	
	18.2	Downcomers 564	
		Packings 565	
	18.4	How Packings and Trays Compare on Plugging Resistance 565	
		18.4.1 Trays versus Trays 565	
		18.4.2 Trays versus Packings 566	
		18.4.3 Packings versus Packings 567	
	18.5	Limited Zone Only 567	
	18.6	Draw, Exchanger, and Vent Lines 569	
	18.7	Feed and Inlet Lines 570	
	18.8	Instrument Lines 570	
19.	Coki	ng: Part of Number 1 on Tower Top 10 Malfunctions	571
	19.1	Insufficient Wash Flow Rate, Refinery Vacuum Towers 571	
	19.2	Other Causes, Refinery Vacuum Towers 572	
	19.3	Slurry Section, FCC Fractionators 573	
	19.4	Other Refinery Fractionators 574	
	19.5	Nonrefinery Fractionators 574	
	17.5	Tromomory Tractionators 371	
20.	Leak	S	575
-	20.1	Page 625	
	20.1	Pump, Compressor 575	
	20.2	Heat Exchanger 575 20.2.1 Reboiler Tube 575	
		20.2.1 Reboiler Tube 575 20.2.2 Condenser Tube 576	
		20.2.3 Auxiliary Heat Exchanger (Preheater, Pumparound) 576	
	20.3	Chemicals to/from Other Equipment 577	,
	20.5	20.3.1 Leaking from Tower 577	
		20.3.2 Leaking into Tower 577	
		20.3.3 Product to Product 578	
	20.4	Atmospheric 578	
	20.7	20.4.1 Chemicals to Atmosphere 578	
		20.4.2 Air into Tower 579	
		20.4.2 In mo lower 5/7	
21.	Relie	f and Failure	580
_	21.1	Dalief Paguiraments 500	
	21.1 21.2	Relief Requirements 580 Controls That Affact Palief Paguirements and Fraguency 580	
	21.2	Controls That Affect Relief Requirements and Frequency Relief Causes Tower Damage, Shifts Deposits 580	
	41.3	Rener Causes Tower Damage, Smits Deposits 381	

***	~
XVIII	Contents

21.5	Overpressure Due to Component Entry 581
21.5	Relief Protection Absent or Inadequate 582
21.6	Line Ruptures 583
21.7	All Indication Lost When Instrument Tap Plugged 584
21.8	Trips Not Activating or Incorrectly Set 584
21.9	Pump Failure 585
21.10	Loss of Vacuum 585
21.11	Power Loss 585
•	Packing, and Tower Damage: Part of Number 3 on the
<u>-</u>	Malfunctions 586
22.1	Vacuum 586
22.2	Insufficient Uplift Resistance 587
22.3	Uplift Due to Poor Tightening during Assembly 587
22.4	Uplift Due to Rapid Upward Gas Surge 589
22.5	Valves Popping Out 590
22.6	Downward Force on Trays 590
22.7	Trays below Feed Bent Up, above Bent Down and Vice Versa 591
22.8	Downcomers Compressed, Bowed, Fallen 592
22.9	Uplift of Cartridge Trays 593
22.10	Flow-Induced Vibrations 593
22.11 22.12	Compressor Surge 594 Packing Carryover 595
22.12	Packing Carryover 595
	Malting Prackage of Plantic Packing 505
22.13	Melting, Breakage of Plastic Packing 595
22.13 22.14	Damage to Ceramic Packing 595
22.13	· · · · · · · · · · · · · · · · · · ·
22.13 22.14 22.15 3. Reboi	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596
22.13 22.14 22.15 3. Reboi	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT, Pinching 596 23.1.4 Surging 596
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597
22.13 22.14 22.15 3. Reboil Malfu	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597 23.2.1 Leaking Draw Tray or Draw Pan 597
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597 23.2.1 Leaking Draw Tray or Draw Pan 597 23.2.2 No Vaporization/Thermosiphon 598
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597 23.2.1 Leaking Draw Tray or Draw Pan 597 23.2.2 No Vaporization/Thermosiphon 598
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT, Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597 23.2.1 Leaking Draw Tray or Draw Pan 597 23.2.2 No Vaporization/Thermosiphon 598 23.2.3 Slug Flow in Outlet Line 599
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT , Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597 23.2.1 Leaking Draw Tray or Draw Pan 597 23.2.2 No Vaporization/Thermosiphon 598 23.2.3 Slug Flow in Outlet Line 599 Forced-Circulation Reboilers 599
22.13 22.14 22.15 3. Reboil Malfu 23.1	Damage to Ceramic Packing 595 Damage to Other Packings 595 lers That Did Not Work: Number 9 on the Top 10 nctions 596 Circulating Thermosiphon Reboilers 596 23.1.1 Excess Circulation 596 23.1.2 Insufficient Circulation 596 23.1.3 Insufficient ΔT, Pinching 596 23.1.4 Surging 596 23.1.5 Velocities Too Low in Vertical Thermosiphons 597 23.1.6 Problems Unique to Horizontal Thermosiphons 597 Once-Through Thermosiphon Reboilers 597 23.2.1 Leaking Draw Tray or Draw Pan 597 23.2.2 No Vaporization/Thermosiphon 598 23.2.3 Slug Flow in Outlet Line 599 Forced-Circulation Reboilers 599 Kettle Reboilers 599


	23.5	Internal Reboilers 602				
	23.6	Kettle and Thermosiphon Reboilers in Series 603				
	23.7	<u>-</u>				
		23.7.1 Inability to Start 603				
		23.7.2 Liquid Draw and Vapor Return Problems 603				
		23.7.3 Hydrates 603				
		23.7.4 Pinching 604				
		23.7.5 Control Issues 604				
	23.8	All Reboilers, Boiling Side 604				
		23.8.1 Debris/Deposits in Reboiler Lines 604				
		23.8.2 Undersizing 604				
		23.8.3 Film Boiling 604				
	23.9	All Reboilers, Condensing Side 605				
		23.9.1 Non condensables in Heating Medium 605				
		23.9.2 Loss of Condensate Seal 605				
		23.9.3 Condensate Draining Problems 606				
		23.9.4 Vapor/Steam Supply Bottleneck 606				
24.	Cond	ensers That Did Not Work 607				
	24.1	Inerts Blanketing 607				
		24.1.1 Inadequate Venting 607				
		24.1.2 Excess Lights in Feed 608				
	24.2	Inadequate Condensate Removal 608				
		24.2.1 Undersized Condensate Lines 608				
		24.2.2 Exchanger Design 609				
	24.3	Unexpected Condensation Heat Curve 609				
	24.4	Problems with Condenser Hardware 610				
	24.5	Maldistribution between Parallel Condensers 611				
	24.6	Flooding/Entrainment in Partial Condensers 611				
	24.7	Interaction with Vacuum and Recompression Equipment 612				
	24.8	Others 612				
25.	Misle	ading Measurements: Number 8 on the Top 10 Malfunctions 613				
	25.1	Incorrect Readings 613				
	25.2	Meter or Taps Fouled or Plugged 614				
	25.3	Missing Meter 615				
		Incorrect Meter Location 615				
	25.5	Problems with Meter and Meter Tubing Installation 616				
		25.5.1 Incorrect Meter Installation 616				
		25.5.2 Instrument Tubing Problems 616				
	25.6	Incorrect Meter Calibration, Meter Factor 617				
	25.7	Level Instrument Fooled 617				
		25.7.1 By Froth or Foam 617				
		25.7.2 By Oil Accumulation above Aqueous Level 618				
		25.7.3 By Lights 619				

		25.7.4	By Radioactivity (Nucleonic Meter) 619	
			Interface-Level Metering Problems 619	
	25.8		Readings Ignored 619	
	25.9	Electric	Storm Causes Signal Failure 619	
26.	Cont	rol Syste	em Assembly Difficulties	620
	26.1	No Mat	terial Balance Control 620	
	26.2	Control	lling Two Temperatures/Compositions	
			neously Produces Interaction 621	
	26.3	Problem	ns with the Common Control Schemes, No Side Draws	622
		26.3.1	Boil-Up on TC/AC, Reflux on FC 622	
		26.3.2	Boil-Up on FC, Reflux on TC/AC 623	
		26.3.3	Boil-Up on FC, Reflux on LC 624	
		26.3.4	Boil-Up on LC, Bottoms on TC/AC 625	
		26.3.5	Reflux on Base LC, Bottoms on TC/AC 626	
	26.4	Probler	ns with Side-Draw Controls 626	
		26.4.1	Small Reflux below Liquid Draw Should Not Be	
			on Level or Difference Control 626	
		26.4.2	Incomplete Material Balance Control with Liquid Draw	628
		26.4.3	Steam Spikes with Liquid Draw 628	
		26.4.4	Internal Vapor Control makes or Breaks	
			Vapor Draw Control 628	
		26.4.5	Others 628	
27.	When	re Do Te	mperature and Composition Controls Go Wrong?	629
	27.1	Temper	rature Control 629	
		27.1.1	No Good Temperature Control Tray 629	
		27.1.2	Best Control Tray 630	
		27.1.3	Fooling by Nonkeys 630	
		27.1.4	Averaging (Including Double Differential) 631	
		27.1.5	Azeotropic Distillation 631	
			Extractive Distillation 631	
		27.1.7		
	27.2		e-Compensated Temperature Controls 632	
			ΔT Control 632	
			Other Pressure Compensation 633	
	27.3	-	er Control 633	
		27.3.1	Obtaining a Valid Analysis for Control 633	
		27.3.2	Long Lags and High Off-Line Times 633	
		27.3.3	Intermittent Analysis 634	
		27.3.4	Handling Feed Fluctuations 635	
		27.3.5	Analyzer–Temperature Control Cascade 635	
		27.3.6	Analyzer On Next Tower 635	

28.	Misbe	ehaved Pressure, Condenser, Reboiler, and Preheater Controls	636				
	28.1	Pressure Controls by Vapor Flow Variations 636					
	28.2	Flooded Condenser Pressure Controls 637					
		28.2.1 Valve in the Condensate, Unflooded Drum 637					
		28.2.2 Flooded Drum 637					
		28.2.3 Hot-Vapor Bypass 637					
		28.2.4 Valve in the Vapor to the Condenser 639					
	28.3	Coolant Throttling Pressure Controls 640					
		28.3.1 Cooling-Water Throttling 640					
		28.3.2 Manipulating Airflow 640					
		28.3.3 Steam Generator Overhead Condenser 640					
		28.3.4 Controlling Cooling-Water Supply Temperature 640					
	28.4 Pressure Control Signal 641						
		28.4.1 From Tower or from Reflux Drum? 641					
		28.4.2 Controlling Pressure via Condensate Temperature 641					
	28.5 Throttling Steam/Vapor to Reboiler or Preheater 641						
	28.6	Throttling Condensate from Reboiler 642					
	28.7	Preheater Controls 643					
<u>29.</u>	Misce	ellaneous Control Problems	644				
	29.1	Interaction with the Process 644					
	29.2	ΔP Control 644					
	29.3	Flood Controls and Indicators 644					
	29.4	Batch Distillation Control 645					
	29.5	Problems in the Control Engineer's Domain 645					
	29.6	Advanced Controls Problems 646					
		29.6.1 Updating Multivariable Controls 646					
		29.6.2 Advanced Controls Fooled by Bad Measurements 646					
		29.6.3 Issues with Model Inaccuracies 647					
		29.6.4 Effect of Power Dips 647					
		29.6.5 Experiences with Composition Predictors in					
		Multivariable Controls 647					
Ref	References 649						
Ind	lex	669					

About the Author

713



Preface

"To every problem, there's always an easy solution—neat, plausible, and wrong."

—Mencken's Maxim

The last half-century has seen tremendous progress in distillation technology. The introduction of high-speed computers revolutionized the design, control, and operation of distillation towers. Invention and innovation in tower internals enhanced tower capacity and efficiency beyond previously conceived limits. Gamma scans and laser-guided pyrometers have provided troubleshooters with tools of which, not-solong-ago, they would only dream. With all these advances, one would expect the failure rate in distillation towers to be on the decline, maybe heading towards extinction as we enter the 21st century. Our recent survey of distillation failures (255) brought disappointing news: Distillation failures are not on the path to extinction. Instead, the tower failure rate is on the rise and accelerating.

Our survey further showed that the rise is not because distillation is moving into new, unchartered frontiers. By far, the bulk of the failures have been repetitions of previous ones. In some cases, the literature describes 10–20 repetitions of the same failure. And for every case that is reported, there are tens, maybe hundreds, that are not.

In the late 1980s, I increased tray hole areas in one distillation tower in an attempt to gain capacity. Due to vapor cross flow channeling, a mechanism unknown at the time, the debottleneck went sour and we lost 5% capacity. Half a year of extensive troubleshooting, gamma scans, and tests taught us what went wrong and how to regain the lost capacity. We published extensively on the phenomenon and how to avoid. A decade later, I returned to investigate why another debottleneck (this time by others) went sour at the same unit. The tower I previously struggled with was replaced by a larger one, but the next tower in the sequence (almost the same hydraulics as the first) was debottlenecked... by increasing tray hole areas!

It dawned on me how short a memory the process industries have. People move on, the lessons get forgotten, and the same mistakes are repeated. It took only one decade to forget. Indeed, people moved on: only one person (beside me) that experienced the 1980s debottleneck was involved in the 1990s efforts. This person actually questioned

the debottleneck proposal, but was overruled by those who did not believe it will happen again.

Likewise, many experiences are repeatedly reported in the literature. Over the last two decades, there has been about one published case history per year of a tower flooding prematurely due to liquid level rising above the reboiler return nozzle, or of a kettle reboiler bottleneck due to an incorrectly compiled force balance. One would think that had we learned from the first case, all the repetitions could have been avoided. And again, for every case that is reported, there are tens, maybe hundreds that are not.

Why are we failing to learn from past lessons? Mergers and cost-cuts have retired many of the experienced troubleshooters and thinly spread the others. The literature offers little to bridge the experience gap. In the era of information explosion, databases, and computerized searches, finding the appropriate information in due time has become like finding a needle in an evergrowing haystack. To locate a useful reference, one needs to click away a huge volume of wayward leads. Further, cost-cutting measures led to library closures and to curtailed circulation and availability of some prime sources of information, such as, AIChE meeting papers.

The purpose of this book is pick the needles out of the haystack. The book collects lessons from past experiences and puts them in the hands of troubleshooters in a usable form. The book is made up of two parts: the first is a collection of "war stories," with the detailed problems and solutions. The second part is a database mega-table which presents summaries of all the "war stories" I managed to find in the literature. The summaries include some key distillation-related morals. For each of these, the literature reference is described fully, so readers can seek more details. Many of the case histories could be described under more than one heading, so extensive cross references have been included.

If an incident that happened in your plant is described, you may notice that some details could have changed. Sometimes, this was done to make it more difficult for people to tell where the incident occurred. At other times, this was done to simplify the story without affecting the key lessons. Sometimes, the incident was written up several years after it occurred, and memories of some details faded away. Sometimes, and this is the most likely reason, the case history did not happen in your plant at all. Another plant had a similar incident.


The case histories and lessons drawn are described to the best of my and the contributors' knowledge and in good faith, but do not always correctly reflect the problems and solutions. Many times I thought I knew the answer, possibly even solved the problem, only to be humbled by new light or another experience later. The experiences and lessons in the book are not meant to be followed blindly. They are meant to be taken as stories told in good faith, and to the best of knowledge and understanding of the author or contributor. We welcome any comments that either affirm or challenge our perception and understanding.

If you picked the book, you expressed interest in learning from past experiences. This learning is an essential major step along the path traveled by a good troubleshooter or designer. Should you select this path, be prepared for many sleepless nights in the plant, endless worries as to whether you have the right answer, tests that will

shatter your favorite theories, and many humbling experiences. Yet, you will share the glory when your fix or design solves a problem where others failed. You will enjoy harnessing the forces of nature into a beneficial purpose. Last but not least, you will experience the electric excitement of the "moments of insight," when all the facts you have been struggling with for months suddenly fall together into a simple explanation. I hope this book helps to get you there.

HENRY Z. KISTER

March 2006



Acknowledgments


Many of the case histories reported in this book have been invaluable contributions from colleagues and friends who kindly and enthusiastically supported this book. Many of the contributors elected to remain anonymous. Kind thanks are due to all contributors. Special thanks are due to those who contributed multiple case histories, and to those whose names do not appear in print. To those behind-the-scenes friends, I extends special appreciation and gratitude.

Writing this book required breaking away from some of the everyday work demands. Special thanks are due to Fluor Corporation, particularly to my supervisors, Walter Stupin and Paul Walker, for their backing, support and encouragement of this book-writing effort, going to great lengths to make it happen.

Recognition is due to my mentors who, over the years, encouraged my work, immensely contributed to my achievements, and taught me much about distillation and engineering: To my life-long mentor, Walter Stupin, who mentored and encouraged my work, throughout my career at CF Braun and later at Fluor, being a ceaseless source of inspiration behind my books and technical achievements; Paul Walker, Fluor, whose warm encouragement and support have been the perfect motivators for professional excellence and achievement; Professor Ian Doig, University of NSW, who inspired me over the years, showed me the practical side of distillation, and guided me over a crisis early in my career; Reno Zack, who enthusiastically encouraged and inspired my achievements throughout my career at CF Braun; Dick Harris and Trevor Whalley, who taught me about practical distillation and encouraged my work and professional pursuits at ICI Australia; and Jack Hull, Tak Yanagi, and Jim Gosnell, who were sources of teaching and inspiration at CF Braun. The list could go on, and I express special thanks to all that encouraged, inspired, and contributed to my work over the years. Much of my mentors' teachings found their way into the following pages.

Special thanks are due to family members and close friends who have helped, supported and encouraged my work—my mother, Dr. Helen Kister, my father, Dr. John Kister, and Isabel Wu—your help and inspiration illuminated my path over the years.

Last but not least, special thanks are due to Mireille Grey and Stan Okimoto at Fluor, who flawlessly and tirelessly converted my handwritten scrawl into a typed manuscript, putting up with my endless changes and reformats.



How to Use this Book

The use of this book as a story book or bedtime reading is quite straight forward and needs no guidance. Simply select the short stories of specific interest and read them.


More challenging is the use of this book to look for experiences that could have relevance to a given troubleshooting endeavor. Here the database mega-Table in the second part of the book is the key. Find the appropriate subject matter via the table of contents or index, and then explore the various summaries, including those in the cross-references. The database mega-Table also lists any case histories that are described in full in this book. Such case histories will be prefixed "DT" (acronym for Distillation Troubleshooting). For instance, if the mega-Table lists DT2.4, it means that the full experience is reported as case history 2.4 in this book.

The database as well as many of the case histories list only some of the key lessons drawn. The lessons listed are not comprehensive, and omit nondistillation morals (such as the needs for more staffing or better training). The reader is encouraged to review the original reference for additional valuable lessons.

For quick reference, the acronyms used in Distillation Troubleshooting are listed up front, and the literature references are listed alphabetically.

Some of the case histories use English units, others use metric units. The units used often reflect the unit system used in doing the work. The conversions are straightforward and can readily be performed by using the conversion tables in Perry's Handbook (393) or other handbooks.

The author will be pleased to hear any comments, experiences or challenges any readers may wish to share for possible inclusion in a future edition. Also, the author is sure that despite his intensive literature search, he missed several invaluable references, and would be very grateful to receive copies of such references. Feedback on any errors, as well as rebuttal to any of the experiences described, is also greatly appreciated and will help improve future editions. Please write, fax or e-mail to Henry Z. Kister, Fluor, 3 Polaris Way, Aliso Viejo, CA 92698, phone 1-949-349-4679; fax 1-949-349-2898; e-mail henry.kister@fluor.com.



Abbreviations

AC Analyzer control
AGO Atmospheric gas oil
aMDEA Activated MDEA
AMS Alpha-methyl styrene
APC adaptive process control

AR on-line analyzer

ASTM American Society for Testing and Materials

atm atmospheres, atmospheric

B Bottoms
barg bars, gauge
BFW Boiler feed water

BMD 2-bromomethyl-1, 3-dioxolane

BPD Barrels per day
BPH Barrels per hour
BSD bottom side draw

BTEX Benzene, toluene, ethylbenzene, xylene

BTX Benzene, toluene, xylene

 $C_1, C_2, C_3...$ Number of carbon atoms in compound

CAT computed axial tomography

Cat Catalytic

C-factor Vapor capacity factor, defined by equation 2 in Case Study 1.14

CFD computational fluid dynamics

CHP cumene hydroperoxide

CO₂ Carbon dioxide
Co. Company
CS Carbon steel
CT Chimney Tray
CTC Carbon tetrachloride

CW Cooling water
CWR Cooling water return

CWS Cooling water supply

D Distillate

D86 ASTM atmospheric distillation test of petroleum fraction

xxxii Abbreviations

DAA diacetone alcohol
DC₁ Demethanizer
DC₂ Deethanizer
DC₃ Depropanizer
DC₄ Debutanizer
DC₅ Depentanizer
DCM Dichloromethane

DCS Distributed control system

DEA Diethanol amine

DFNB 2, 4-difluoronitrobenzene

DIB Deisobutanizer
DMAC dimethylacetamide
DMC Dynamic matrix control
DMF Dimethylformamide
DMSO Dimethyl sulphoxide

DO Decant oil dP Same as ΔP

DQI Distribution quality index DRD distillation region diagram

dT Same as ΔT

DT Distillation troubleshooting (this book)

EB Energy balance; ethylbenzene

ED extractive distillation EDC Ethylene dichloride EG Ethylene glycol

EGEE Ethylene glycol monoethyl ether

EO ethylene oxide EOR End of run

ETFE Ethylene tetrafluoroethylene, a type of teflon

FC Flow control

FCC Fluid catalytic cracker

FI Flow indicator fph feet per hour FR Flow recorder FS Flow Switch

ft Feet gal gallons

GC Gas chromatographs

GC-MS Gas chromatography-mass spectrometry

gpm gallons per minute

GS A process of concentrating deutrium by dual-temperature isotope exchange between water and hydrogen sulfide with no catalyst

 $\begin{array}{ll} h & hours \\ H_2 & Hydrogen \\ H_2O & Water \end{array}$

H₂S Hydrogen sulfide HA Hydroxyl amine

HAZOP Hazard and operability study

HC Hydrocarbon

HCGO Heavy coker gas oil
HCl Hydrogen chloride
HCN Hydrogen cyanide
HCO Heavy cycle oil
HD Heavy diesel

HETP Height equivalent of a theoretical plate

HF Hydrogen fluoride

Hg Mercury
HK Heavy key
HN Heavy naphtha
HP High pressure
HR High reflux
HSS Heat-stable salts
HV hand valve

HVGO Heavy vacuum gas oil
IBP Initial boiling point
ICO intermediate cycle oil
ID Internal diameter
IK Intermediate key

in. inch

IPA Isopropyl alcohol IPE Isopropyl ether

IR Infrared

IVC Internal vapor control

kPa Kilopascals kPag Kilopascals gage

lb pounds LC Level control LCGO Light coker gas oil LCO Light cycle oil Light diesel LD LI Level indicator LK Light key LL Liquid-liquid

LMTD Log mean temperature difference

LP Low pressure

LPB Loss Prevention Bullletin

LPG Liquefied petroleum gas; refers to C₃ and C₄ hydrocarbons

LR Low reflux LT Level transmitter

L/V Liquid-to-vapor molar ratio

xxxiv Abbreviations

LVGO Light vacuum gas oil

m meters

MB Material balance

MDEA Methyl diethanol amine
MEA Monoethanol amine
MEK Methyl ethyl ketone
MF Main fractionator
min Minutes or minimum

MISO Multiple inputs, single output

mm millimeters

MNT Mononitrotoluene
MOC Management of change
MP Medium Pressure

MPC Model predictive control

mpy mils per year, refers to a measure of conosion rates. 1 mil is 1/1000 inch

MSDS Material safety data sheets

MTS Refers to a proprietary liquid distributor marketed by

Sulzer under license from Dow Chemical

MV Manual valve

MVC Multivariable control, or more volitle component

N₂ nitrogen

NC Normally closed
NGL Natural gas liquids
NNF Normally no flow
NO Normally open

NPSH Net positive suction head

NRTL Nonrandom two liquid; refers to a popular VLE prediction method

NRU Nitrogen rejection unit

 O_2 oxygen

ORS Oxide redistillation still

OSHA Occupational Safety and Health Administration

PA Pumparound

P&ID Process and instrumentation diagram

PC Pressure control
PCV Pressure control valve
PI Pressure indicator

PR Peng–Robinson; refers to a popular VLE prediction method

psi pounds per square inch

psia psi absolute psig psi gauge

PSV Pressure safety valve
PT Pressure transmitter
PVC Polyvinyl chloride
PVDF Polyvynilidene fluoride

R22 Freon 22

R/D Reflux-to-distillate molar ratio

Ref. Reference
Refrig Refrigeration
RO Restriction orifice
RVP Reid vapor pressure

s seconds

SBE Di-Sec-butyl ether

sec. secondary
SG specific gravity
SPA Slurry pumparound

SRK Soave, Redlich, and Kwong; refers to a popular VLE method

SS Stainless steel

STM Steam T/A Turnaround

TBP True boiling point
TC Temperature control
TCE Trichloroethylene

TDC Temperature difference controller

TEA Triethanol amine
TEG Triethylene glycol
TI Temperature indicator

Ti Titanium

TRC temperature recorder/controller

UNIQAC Unified quasi-chemical; refers to a popular VLE prediction method

VAM Vinyl acetate monomer

V/B Stripping ratio, i.e., molar ratio of stripping section

vapor flow rate to tower bottom flow rate

VCFC Vapor cross-flow channeling VCM Vinyl chloride monomer

VGO Vacuum gas oil


VLE Vapor-liquid equilibrium

VLLE Vapor-liquid-liquid equilibrium

VOC Volatile organic carbon

vol Volume w.g. water gage wt by weight

 ΔP Pressure difference ΔT Temperature difference



Chapter 1

Troubleshooting Distillation Simulations

It may appear inappropriate to start a distillation troubleshooting book with a malfunction that did not even make it to the top 10 distillation malfunctions of the last half century. Simulations were in the 12th spot (255). Countering this argument is that simulation malfunctions were identified as the fastest growing area of distillation malfunctions, with the number reported in the last decade about triple that of the four preceding decades (252). If one compiled a distillation malfunction list over the last decade only, simulation issues would have been in the equal 6th spot. Simulations have been more troublesome in chemical than in refinery towers, probably due to the difficulty in simulating chemical nonidealities. The subject was discussed in detail in another paper (247).

The three major issues that affect simulation validity are using good vapor-liquid equilibrium (VLE) predictions, obtaining a good match between the simulation and plant data, and applying graphical techniques to troubleshoot the simulation (255). Case histories involving these issues account for about two-thirds of the cases reported in the literature. Add to this ensuring correct chemistry and correct tray efficiency, these items account for 85% of the cases reported in the literature.

A review of the VLE case studies (247) revealed major issues with VLE predictions for close-boiling components, either a pair of chemicals [e.g., hydrocarbons (HCs)] of similar vapor pressures or a nonideal pair close to an azeotrope. Correctly estimating nonidealities has been another VLE troublespot. A third troublespot is characterization of heavy components in crude oil distillation, which impacts simulation of refinery vacuum towers. Very few case histories were reported with other systems. VLE prediction for reasonably ideal, relatively high volatility systems (e.g., ethane–propane or methanol–ethanol) is not frequently troublesome.

The major problem in simulation validation appears to be obtaining a reliable, consistent set of plant data. Getting correct numbers out of flowmeters and laboratory analyses appears to be a major headache requiring extensive checks and rechecks. Compiling mass, component, and energy balances is essential for catching a

misleading flowmeter or composition. One specific area of frequent mismatches between simulation and plant data is where there are two liquid phases. Here comparison of measured to simulated temperature profiles is invaluable for finding the second liquid phase. Another specific area of frequent mismatches is refinery vacuum towers. Here the difficult measurement is the liquid entrainment from the flash zone into the wash bed, which is often established by a component balance on metals or asphaltenes.

The key graphical techniques for troubleshooting simulations are the McCabe—Thiele and Hengstebeck diagrams, multicomponent distillation composition profiles, and in azeotropic systems residue curve maps. These techniques permit visualization and insight into what the simulation is doing. These diagrams are not drawn from scratch; they are plots of the composition profiles obtained by the simulation using the format of one of these procedures. The book by Stichlmair and Fair (472) is loaded with excellent examples of graphical techniques shedding light on tower operation.

In chemical towers, reactions such as decomposition, polymerization, and hydrolysis are often unaccounted for by a simulation. Also, the chemistry of a process is not always well understood. One of the best tools for getting a good simulation in these situations is to run the chemicals through a miniplant, as recommended by Ruffert (417).

In established processes, such as separation of benzene from toluene or ethanol from water, estimating efficiency is quite trouble free in conventional trays and packings. Problems are experienced in a first-of-a-kind process or when a new mass transfer device is introduced and is on the steep segment of its learning curve.

Incorrect representation of the feed entry is troublesome if the first product leaves just above or below or if some chemicals react in the vapor and not in the liquid. A typical example is feed to a refinery vacuum tower, where the first major product exits the tower between 0.5 and 2 stages above the feed.

The presentation of liquid and vapor rates in the simulation output is not always user friendly, especially near the entry of subcooled reflux and feeds, often concealing higher vapor and liquid loads. This sometimes precipitates underestimates of the vapor and liquid loads in the tower.

Misleading hydraulic predictions from simulators is a major troublespot. Most troublesome have been hydraulic predictions for packed towers, which tend to be optimistic, using both the simulator methods and many of the vendor methods in the simulator (247, 254). Simulation predictions of both tray and packing efficiencies as well as downcomer capacities have also been troublesome. Further discussion is in Ref. 247.

CASE STUDY 1.1 METHANOL IN C₃ SPLITTER OVERHEAD?

Installation Olefins plant C₃ splitter, separating propylene overhead from propane at pressures of 220–240 psig, several towers.

Background Methanol is often present in the C_3 splitter feed in small concentrations, usually originating from dosing upstream equipment to remove hydrates. Hydrates are loose compounds of water and HCs that behave like ice, and methanol is used like antifreeze. The atmospheric boiling points of propylene, propane, and methanol are -54, -44, and 148° F, respectively. The C_3 splitters are large towers, usually containing between 100 and 300 trays and operating at high reflux, so they have lots of separation capability.

Problem Despite the large boiling point difference (about 200°F) and the large tower separation capability, some methanol found its way to the overhead product in all these towers. Very often there was a tight specification on methanol in the tower overhead.

Cause Methanol is a polar component, which is repelled by the nonpolar HCs. This repulsion is characterized by a high activity coefficient. With the small concentration of methanol in the all-HC tray liquid, the repulsion is maximized; that is, the activity coefficient of methanol reaches its maximum (infinite dilution) value. This high activity coefficient highly increases its volatility, to the point that it almost counterbalances the much higher vapor pressure of propylene. The methanol and propylene therefore become very difficult to separate.

Simulation All C₃ splitter simulations that the author worked with have used equations of state, and these were unable to correctly predict the high activity coefficient of the methanol. They therefore incorrectly predicted that all the methanol would end up in the bottom and none would reach the tower top product.

Solution In most cases, the methanol was injected upstream for a short period only, and the off-specification propylene product was tolerated, often blended in storage. In one case, the methanol content of the propylene was lowered by allowing some propylene out of the C_3 splitter bottom at the expense of lower recovery.

Related Experience A very similar experience occurred in a gas plant depropanizer separating propane from butane and heavier HCs. Here the methanol ended in the propane product.

Other Related Experiences Several refinery debutanizers that separated C_3 and C_4 [liquefied petroleum gases (LPGs)] from C_5 and heavier HCs (naphtha) contained small concentrations of high-boiling sulfur compounds. Despite their high boiling points (well within the naphtha range), these high boilers ended in the overhead LPG product. Sulfur compounds are polar and are therefore repelled by the HC tray liquid. The repulsion (characterized by their infinite dilution activity coefficient) made these compounds volatile enough to go up with the LPG. Again, tower simulations that were based on equations of state incorrectly predicted that these compounds would end up in the naphtha.

4 Chapter 1 Troubleshooting Distillation Simulations

In one refinery and one petrochemical debutanizer, mercury compounds with boiling points in the gasoline range were found in the LPG, probably reaching it by a similar mechanism.

CASE STUDY 1.2 WATER IN DEBUTANIZER: QUO VADIS?

Installation A debutanizer separating C_4 HCs from HCs in the C_5 – C_8 range. Feed to the tower was partially vaporized in an upstream feed-bottom interchanger. The feed contained a small amount of water. Water has a low solubility in the HCs and distilled up. The reflux drum was equipped with a boot designed to gravity-separate water from the reflux.

Problem When the feed contained a higher concentration of water or the reflux boot was inadvertently overfilled, water was seen in the tower bottoms.

Cause The tower feed often contained caustic. Caustic deposits were found in the tower at shutdown. Sampling the water in the tower bottom showed a high pH. Analysis showed that the water in the bottom was actually concentrated caustic solution.

Prevention Good coalescing of water and closely watching the interface level in the reflux drum boot kept water out of the feed and reflux. Maximizing feed preheat kept water in the vapor.

CASE STUDY 1.3 BEWARE OF HIGH HYDROCARBON VOLATILITIES IN WASTEWATER SYSTEMS

Benzene was present in small concentration, of the order of ppm, in a refinery wastewater sewer system. Due to the high repulsion between the water and benzene molecules, benzene has a high activity coefficient, making it very volatile in the wastewater.

Poor ventilation, typical of sewer systems, did not allow the benzene to disperse, and it concentrated in the vapor space above the wastewater. The lower explosive limit of benzene in air is quite low, about a few percent, and it is believed that the benzene concentration exceeded it at least in some locations in the sewer system.

The sewer system had one vent pipe discharging at ground level without a gooseneck. A worker was doing hot work near the top of that pipe. Sparks are believed to have fallen into the pipe, igniting the explosive mixture. The pipe blew up into the worker's face, killing him.

Morals

- Beware of high volatilities of HCs and organics in a wastewater system.
- Avoid venting sewer systems at ground level.

CASE STUDY 1.4 A HYDROCARBON VLLE METHOD USED FOR AQUEOUS FEED EQUILIBRIUM

Contributed by W. Randall Hollowell, CITGO, Lake Charles, Louisiana

Installation Feed for a methanol—water separation tower was the water—methanol phase from a three-phase gas—oil—aqueous separator. Gas from the separator was moderately high in H₂S and in CO₂. Tower preliminary design used a total overhead condenser to produce 95% methanol. Methanol product was cooled and stored at atmospheric pressure. Off gas from storage was not considered a problem because the calculated impurities in the methanol product were predominantly water.

Problem Tower feed had been calculated with a standard gas-processing vapor-liquid-liquid equilibrium (VLLE) method (Peng-Robinson equation of state). A consultant noted that the VLLE method applied only to aqueous phases that behaved like pure water and only to gas-phase components that had low solubility in the aqueous phase.

The large methanol content of the aqueous phase invalidated these feed composition calculations. Every gas component was far more soluble in the tower feed than estimated. The preliminary tower design would have produced a methanol product with such a high H₂S vapor pressure that it could not be safely stored in the atmospheric tank.

Better Approach Gas solubility in a mixed, non-HC solvent (methanol and water) is a Henry's constant type of relationship for which process simulation packages often do not have the methods and/or parameters required.

Addition of a pasteurization section to the top of a tower is a common fix for removing light impurities from the distillate product. After condensing most of the overhead vapor, a small overhead vent gas stream is purged out of the tower to remove light ends. Most or all of the overhead liquid is refluxed to minimize loss of desired product in the purges. The pasteurization section typically contains 3–10 trays or a short packed bed, used to separate light ends from the distillate product. The distillate product is taken as a liquid side draw below the pasteurization trays. The side draw may be stripped to further reduce light ends. The vent gas may be refrigerated and solvent washed or otherwise treated to reduce loss of desired product.

Solution An accurate, specific correlation (outside of the process simulation package) was used to calculate H₂S and CO₂ concentration in the methanol-water tower feed. Solubility of HC components was roughly estimated because they were at relatively low concentrations in the tower feed. A high-performance coalescer was used to minimize liquid HC droplets in the tower feed.

A pasteurization section was added to the top of the tower. The overhead vent gas purge stream was designed to remove most of the H₂S, CO₂, and light HCs. Downstream recovery of methanol from the vent gas and stripping of the methanol product side draw were considered but found to be uneconomical.

Moral Poor simulation and design result from poor selection of VLE and VLLE methods. Computer output does not include a warning when the selected VLE method produces garbage.

CASE STUDY 1.5 MODELING TERNARY MIXTURE USING BINARY INTERACTION PARAMETERS

Contributed by Stanislaw K. Wasylkiewicz, Aspen Technology, Inc., Calgary, Alberta, Canada

This case study describes a frequently encountered modeling problem during simulation of heterogeneous azeotropic distillation. Phase diagrams are invaluable for troubleshooting this type of simulation problems.

Distillation Simulation A sequence of distillation columns for separation of a mixture containing water and several organic alcohols was set up in a simulator. Since some of the alcohols are not fully miscible with water, a nonrandom two-liquid (NRTL) model was selected to model VLLE in the system. At atmospheric pressure, the vapor phase was treated as an ideal gas.

Problem Simulation of the sequence of distillation columns never converged, giving many warnings about flash failures.

Investigation For the three key components (methanol, water, and *n*-butanol) a phase diagram was created (508) (Fig. 1.1*a*). As expected, the water–methanol and methanol–*n*-butanol edges are homogeneous and the water–*n*-butanol edge contained an immiscibility gap. Surprisingly, the three-liquid region and three two-liquid regions covered almost the entire composition space. Since water and methanol, as well as butanol and methanol, are fully miscible, the diagram should have been dominated by a single-liquid region. Just looking at the phase diagram one can conclude that the model is not correct.

Analysis Binary interaction parameters for activity models used for VLLE calculations are published for thousands of components [see, e.g., DECHEMA (158) series]. They are regressed based on various experimental data and usually fit the experimental points quite well. NRTL, UNIQUAC, and Wilson models extend these binary data to multicomponent systems without requiring additional ternary, quaternary, and so on, interaction parameters. That is why these models are so popular for modeling VLE for strongly nonideal azeotropic mixtures. This extension, however, is not always performed correctly by the model.

For the ternary mixture methanol-water-n-butanol, the binary interaction parameters have been taken from DECHEMA (158). Some of them are recommended values. All of them describe all the binary pairs very well. But what they predict when combined together can be seen in Figure 1.1a. Notice that to create this VLLE diagram an extremely robust flash calculation with stability test is essential. Without a reliable global stability test, flash calculation can easily fail at some points in this component space or give unstable solutions (526).




Figure 1.1 Phase diagram for nonideal system methanol-water-*n*-butanol, based on extension of good binary data using NRTL model: (*a*) incorrect extension; (*b*) correct extension.

Solution Another set of binary interaction parameters was carefully selected and a new phase diagram was recreated (34). The VLLE changed dramatically (Fig. 1.1b). There is no more three-liquid phase region and only one two-liquid phase region covers only a small part of the composition space. After proper selection of interaction parameters of the thermodynamic model, the sequence of distillation columns converged quickly without any problems.

Morals

- To simulate multicomponent, nonideal distillation, the behavior of the mixture must be carefully verified, starting from binary mixtures, then ternary subsystems, and so on.
- Since there may be many pairs of binary interaction parameters of an activity thermodynamic model that describe behavior of a binary mixture equally well, it is recommended to select one with the lowest absolute values. It is our experience that such values extrapolate better to multicomponent mixtures.
- To correctly create a multicomponent, nonideal VLLE model, an extremely robust VLLE calculation routine with a reliable global stability test is a must [even if liquid-liquid (LL) split is not expected].
- Because of their visualization capabilities, VLLE phase diagrams are invaluable (for ternary and quaternary mixtures) for verification of thermodynamic models used in distillation simulations.

CASE STUDY 1.6 VERY LOW CONCENTRATIONS REQUIRE EXTRA CARE IN VLE SELECTION

Contributed by W. Randall Hollowell, CITGO, Lake Charles, Louisiana

Problem Bottoms from a tower recovering methanol from a methanol–water mixture contained 6 ppm methanol, exceeding the maximum specification of 4 ppm required for discharging to the ocean.

Investigation A consultant pointed out that unusual hydrogen-bonding behavior had been reported at very low concentration of methanol in water. He recommended use of the UNIQUAC equation.

Wilson's equation is generally the method of choice for alcohol-water mixtures when there is no unusual behavior. The more complex NRTL equation is the usual choice for systems that cannot be handled by Wilson's equation. The UNIQUAC equation often applies to systems with chemicallike interactions (i.e., hydrogen bonding, which behaves like weak chemical bonding) that neither Wilson's nor the NRTL equations can represent.

Solution Schedule constraints precluded independently developing UNIQUAC parameters. Various process simulation packages were checked for methanol-water VLE with Wilson's, NRTL, and UNIQUAC equations. All of the equations in all of the packages gave essentially the same VLE, except that UNIQUAC in one major simulator gave lower methanol relative volatilities (by as much as 15%) at very low methanol concentrations. This package executed much slower than the other alternatives. The only methanol concentration predictions that were in line with the field data came from this UNIQAC equation.

Postmortem Exceptions to the typical choices of chemical VLE methods are often not reflected in process simulation packages. For this case, the same data base was probably used by all of the process simulation packages for the regression of UNIQUAC parameters. Predicting VLE for high-purity mixture often requires extrapolation of activity coefficients. Only one method and one simulation package did a good extrapolation to the low-methanol end. Cross checking of VLE equations and packages is a useful way to identify potential problems.

CASE STUDY 1.7 DIAGRAMS TROUBLESHOOT ACETIC ACID DEHYDRATION SIMULATION

Contributed by Stanislaw K. Wasylkiewicz, Aspen Technology, Inc., Calgary, Alberta, Canada

This case study describes a typical thermodynamic modeling problem in distillation simulation and an application of residue curve maps for troubleshooting and proper model selection. The problem described here happened far too many times for many of our clients.

Dehydration of Acetic Acid At atmospheric pressure, there is no azeotrope in the binary mixture of water and acetic acid. However, there is a tangent pinch close to pure water. This makes this binary separation very expensive if only a small concentration of acetic acid in water is allowed (high reflux, many rectifying stages). The difficult separation caused by the tangent pinch can be avoided by adding an entrainer that forms a new heterogeneous azeotrope, moving the distillation profile away from the binary pinch toward the minimum-boiling heterogeneous azeotrope. A decanter can then be used to obtain required distillate purity in far fewer stages than in the original binary distillation (525).

Distillation Simulation A column with top decanter was set up in a simulator to remove water from a mixture containing mostly water and acetic acid. *N*-Butyl acetate was selected as an entrainer. The vapor phase was treated as an ideal gas [*Idel* (227) option]. For the liquid phase, the NRTL model was selected.

Problem Even with an extreme reflux and a large number of stages, the simulation never achieved the required high-purity water in the bottom product of the column.

Troubleshooting For the three key components (water, acetic acid, and the entrainer) a distillation region diagram (DRD) was created (227) to examine the three-component space for multiple liquid regions, azeotropes, and distillation boundaries, as shown in Figure 1.2a.




Figure 1.2 Phase diagram for dehydration of acetic acid using *n*-butyl acetate (*n*-B-C2-oate) entrainer at 1 atm: (*a*) with ideal vapor phase, incorrect; (*b*) accounting for dimerization, correct.

Analysis By examining the DRD, one can easily conclude that there is something wrong with the model. We know that there is no binary acetic acid—water azeotrope at 1 atm. The model (ideal vapor phase) is not capable of describing the system properly. It is well known that carboxylic acids associate in the vapor phase and this has to be taken into account, for example, by vapor dimerization model (158) [*Dimer* option (227)].

Solution Instead of *Idel*, the *Dimer* option was selected (227). The DRD for the system changed tremendously (see Fig. 1.2b). There are no more binary azeotropes between acetic acid and water or n-butyl acetate. After proper selection of the thermodynamic model, the distillation column converged quickly to the required high-purity water specifications in the bottoms.

Morals

- It is important to select the proper thermodynamic model and carefully verify the behavior of the mixture.
- Because of their visualization capabilities, DRDs are extremely useful for evaluating thermodynamic models for ternary and quaternary mixtures.

CASE STUDY 1.8 EVERYTHING VAPORIZED IN A CRUDE VACUUM TOWER SIMULATION

Contributed by W. Randall Hollowell, CITGO, Lake Charles, Louisiana

Problem Atmospheric crude tower bottom was heated, then entered a typical, fuel-type vacuum tower. A hand-drawn curve estimated the atmospheric crude tower bottom composition from assay distillation data for a light crude oil. The simulation estimated that all of the vacuum tower feed vaporized in the flash zone. This was a preposterous result inconsistent with plant data.

Investigation The heaviest assay cuts fell progressively lower than those from another assay of the same crude oil. The heaviest cut was at 850°F atmospheric cut point, compared to the other assay at 1000°F. The assay data were extrapolated on a linear scale to 100% at 1150°F atmospheric boiling point.

The high-boiling part of crude assay data must be carefully assessed. The last several assay points are often poor, particularly when coming from laboratories that cut back on quality control for increased productivity. Crude oils have very high boiling point material. Even light crude oils have material boiling above 1500°F. Extrapolation should be done with percent distilled on a probability-type scale, particularly for light crudes where the slope increases very rapidly on a linear scale.

Solution A new boiling point curve was developed. Another assay was used up to 1000°F cut point, thus reducing the needed extrapolation range. Extrapolation and smoothing of assay data were based upon a probability scale for percent distilled.

A 95% point (whole crude oil basis) of 1400°F was estimated by this extrapolation. Simulation based upon the new boiling point curve was in reasonable agreement with plant data.

Moral Crude oil high-boiling-point data are often poor and must be extrapolated. Experience, following good procedures, and cross checks with plant data are essential for reliable results.

CASE STUDY 1.9 CRUDE VACUUM TOWER SIMULATION UNDERESTIMATES RESIDUE YIELD

Contributed by W. Randall Hollowell, CITGO, Lake Charles, Louisiana

Problem Process simulation estimated much lower vacuum residue yields than obtained from plant towers and from pilot unit runs. Vacuum tower feed boiling point curves were based upon high-temperature gas chromatography (GC) analyses.

Investigation Vacuum tower feed boiling point curves from the GC fell well below curves estimated from assays. The GC analyses assumed that all of the feed oil vaporized in the test and was analyzed.

The highest boiling part of crude oil is too heavy to vaporize in a GC test. Thus the reported GC results did not include the highest boiling part (that above about 1250°F boiling point) of the feed. Simulations based upon this GC data estimated much higher vaporization than actual because they were missing the heaviest part of the feed.

Solution The GC method was modified to include a standard that allowed estimation of how much oil remained in the GC column and was not measured. New GC data and extrapolations of assay data indicated that 10–15% of the feed oil was not vaporized and thus had not been measured by the earlier GC method.

With this improved GC data, simulations agreed well with most of the pilot data. The agreement between simulation and plant data was much better than before but was still not good. This may have been due to poor plant data. Specifically, measured flash zone pressures were often bad.

Moral The analyses used for process simulations must be thoroughly understood.

CASE STUDY 1.10 MISLED BY ANALYSIS

Contributed by Geert Hangx and Marleen Horsels, DSM Research, Geleen, The Netherlands

Problem After a product change in a multipurpose plant, a light-boiling by-product could not be removed to the proper level in the (batch) distillation. The concentration

of the light-boiling component in the final product was 0.5%. It should have been (and was in previous runs) 200 ppm.

Investigation The feed was analyzed by GC per normal procedure. The concentration levels of different components looked good. No significant deviation was found. Then some changes in the distillation were performed, such as

- increasing the "lights fraction" in the batch distillation,
- increasing the reflux ratio during the lights fraction, and
- decreasing the vapor load during the lights fraction.

These changes yielded no significant improvement.

The off-specification product was redistilled. The purity was improved, but still the specification could not be met. The GC analysis was checked (recalibrated) again. Everything was OK.

As all of the above-mentioned actions did not improve the product quality, it seemed that something was wrong with the column. After long discussions it was decided to open the handhole at the top of the column and to have a closer look at the feed distributor. Nothing suspicious was found.

Then it was decided to have a closer look at the analysis again. A gas chromatography—mass spectrometry (GC-MS) analysis was performed. This method showed that the impurity was not the light-boiling component as presumed. This component was a remainder from the previous run in the multipurpose plant. Having a boiling point much closer to the end product, this component could not be separated in the column.

Moral It is a good idea to check the analysis with GC-MS before shutting down a column.

CASE STUDY 1.11 INCORRECT FEED CHARACTERIZATION LEADS TO IMPOSSIBLE PRODUCT SPECIFICATIONS

Contributed by Chris Wallsgrove

Installation A new, entirely conventional depentanizer, recovering a C_5 distillate stream from a $C_5/C_6/C_7$ raffinate mixture from a catalytic reformer/aromatics extraction unit, with some light pyrolysis gasoline feed from an adjacent naphtha-cracking ethylene plant. The column had 30 valve trays, a steam-heated reboiler, and a condenser on cooling water.

Problem The C_5 distillate was guaranteed by the process licensor to contain a maximum of 0.5% wt. C_6 's. Laboratory testing by the on-site laboratory as well

as an impartial third-party laboratory consistently showed about 1.0% of C_6 's in the distillate. Increasing reflux ratio or other operation adjustments did not improve distillate purity.

Troubleshooting The tower was shut down after about 6 weeks of operation to inspect the trays. No damage was found and the trays were reported to be "cleaner than new."

The design simulation was rerun with a variety of options: correlations, convergence criteria, and plant analysis data. The laboratory methods, which were established American Society for Testing and Materials (ASTM) test methods, were reviewed. It became apparent that the feed contained some low-boiling components, such as certain methyl-cyclo C_5 's which were analyzed (correctly) as C_6 's but whose boiling points are in the C_5 range. Since these components would end up in the distillate, it was thermodynamically impossible to achieve the specified performance.

Solution The higher impurity level could be lived with without excessive economic penalty and was accepted.

Moral Correct characterization of feed components is essential even for an "ideal" hydrocarbon mixture.

CASE STUDY 1.12 CAN YOU NAME THE KEY COMPONENTS?

Henry Z. Kister, reference 254. Reproduced with permission. Copyright © (1995) AIChE. All rights reserved

Installation A stabilizer separating C_3 and lighter HCs from nC_4 and heavier operated at its capacity limit. It was to be debottlenecked for a 25% increase in capacity. In addition, it was required to handle several different feedstocks at high throughputs. Due to the tight requirements, thorough tests were conducted and formed the basis for a simulation, which was used for the debottlenecking. We have seen very few tests as extensive and thorough as the stabilizer tests. Two tests were conducted: a high-reflux (HR) test and a low-reflux (LR) test.

Simulation Versus Measurement With two seemingly minor and insignificant exceptions, all reliable measurements compared extremely well with simulated values. In most tests, the accuracy and reliability of the data would have made it difficult to judge whether the exceptions were real or reflected a minor test data problem. In this case, however, consistency checks verified that the exceptions were real. The high accuracy and reliability of the test data made even small discrepancies visible and significant.

The discrepancies occurred in the HR test, while the LR test showed no discrepancy. This was strange because the stabilizer was extremely steady and smooth during the HR test. Any data problems should have occurred in the LR test or in both tests, but not in the HR test alone.

The two exceptions were interlinked. For the HR test, the simulation predicted three times the measured C_5 concentration in the stabilizer overhead, which would lead to a warmer rectifying section. Indeed, the second exception was simulated rectifying section temperatures $2-5^{\circ}F$ warmer than measured.

What Does the Stabilizer Do? At first glance, this question appears stupid. But it turned out to be the key for understanding the test versus the simulation discrepancy.

There was a tight specification on the content of C_3 in the stabilizer bottoms. An excessive amount of C_3 would lead to excessive Reid vapor pressure (RVP) in the bottom, which was undesirable. For similar reasons, it was desirable to minimize iC_4 in the stabilizer bottom, although there was no set specification. In the bottoms, nC_4 and heavier were desirable components and were to be maximized. Any C_5 and heavier, and even nC_4 , ending up in the overhead product incurred an economic penalty because the bottoms were far more valuable than the overheads. There were no set specifications for any of these components.

With the above in mind, what is the stabilizer actually doing? Which pair is the key components? Initially, we thought it was iC_4/nC_4 —but could it have been C_3/iC_4 , nC_4/C_5 , C_3/C_5 , or maybe some other pair? Computer simulations do not answer such questions; Hengstebeck diagrams (211, described in detail in Ref. 251) do.

Hengstebeck diagrams (Fig. 1.3) were prepared from the compositions calculated by the simulation. The HR and LR tests each require one Hengstebeck diagram for each choice of key components: C_3/iC_4 , iC_4/nC_4 , and nC_4/iC_5 . A Hengstebeck diagram for the iC_4/nC_4 separation was included in a more detailed description of the case (254) and showed that this pair behaved the same as the C_3/iC_4 pair.

Figure 1.3a shows that in the HR test, below the feed, the stabilizer effectively separated C_3 and lighter from iC_4 and heavier. The diagram also shows that a limited degree of separation of these components occurred in the top two stages of the rectifying section, but pinching occurred below these. Overall, very little separation of C_3 and lighter from iC_4 and heavier occurred in the rectifying section. The stabilizer essentially behaved as a stripper for separating C_3 and lighter from iC_4 and heavier.

Figure 1.3b shows that in the HR test, above the feed, the stabilizer effectively separated nC_4 and lighter from iC_5 and heavier. It also illustrates that some separation of these components took place in the bottom five stages of the stripping section, but pinching occurred above these.

Together, Figures 1.3a and b underscore that the stripping section of the stabilizer separated C_3 and lighter from iC_4 and heavier and, per Ref. 254, also iC_4 and lighter from nC_4 and heavier. The rectifying section of the stabilizer separated iC_5 and heavier from nC_4 and lighter.




Figure 1.3 Hengstebeck diagrams for stabilizer tests: (a) C_3-iC_4 separation, HR test; (b) nC_4-iC_5 separation, HR test; (c) nC_4-iC_5 separation, LR test. (From Ref. 254. Reproduced with permission. Copyright © (1995) AIChE. All rights reserved.)

In the LR test, the Hengstebeck diagrams for the C_3/iC_4 and iC_4/nC_4 separation were similar to those for the HR test (Fig. 1.3a). In this test, too, the stabilizer stripping section effectively separated C_3 and lighter from iC_4 and heavier and iC_4 and lighter from nC_4 and heavier.

Figure 1.3c indicates that in the LR test, above the feed, the separation of nC_4 and lighter from iC_5 and heavier was pinched. This is different from the HR test, where the rectifying section effectively separated nC_4 and lighter from iC_5 and heavier. The diagram also shows that, as in the HR test, the nC_4/iC_5 separation was pinched in the stripping section.

Overall, the stabilizer behavior in the LR test resembled that of HR test, with the exception that the rectifying section, which separated nC_4 from iC_5 in the HR test, was pinched and did little of this separation in the LR test.

Why the Differences Between Measurement and Simulation? There were two conceivable explanations to the high C_5 concentration in the HR test simulation:

- 1. Inaccuracies in VLE data. Detailed checks of the VLE confirmed that the values used were very good and superior to those predicted by the commercial simulator program, but not perfect. Two relevant inaccuracies were a high C₃/iC₄ volatility prediction for the stripping section and a low C₄/C₅ volatility prediction for the rectifying section.
- 2. Efficiency differences between different binary pairs. This explanation was unlikely because the simulation would suggest a considerably higher efficiency for the higher volatility pair, nC_4/iC_5 , than for the lower volatility pair, iC_4/nC_4 . In contrast, test data (52, 379, 381) show that lower volatility pairs have a higher efficiency.

It was therefore concluded that VLE inaccuracy is the most likely explanation.

One unanswered question is why the differences between measurement and simulation were observed only in the HR test and not in the LR test. Again, the Hengstebeck diagrams provided the answer.

For the HR test, the Hengstebeck diagram (Fig. 1.3b) shows that the rectifying section rectifies C_5 from the nC_4 and lighter. Any error in the relative volatility of the nC_4/iC_5 and nC_4/nC_5 pairs is magnified at each separation stage. The final result is a large difference between measured and simulated top-product compositions.

For the LR test, the Hengstebeck diagram (Fig. 1.3c) shows very little separation of nC_4 from C_5 in the rectifying section. Because of the pinch, an error in the relative volatility of the nC_4/iC_5 and nC_4/nC_5 pairs is not magnified in each separation stage. Such an error, therefore, has little effect on the separation and the temperature profile. For this reason, the LR test simulation gave a good match to measured data.

Would the Inaccuracy Affect the Debottlenecking Predictions? The simulation predicted higher C_5 in the top product, giving a conservative forecast of

the stabilizer performance under test conditions. The remaining question is whether the simulation will continue to give conservative predictions under different process conditions. The question of extrapolating test data into different process conditions is addressed rigorously on pp. 400–405 of Ref. 251. In fact, the analysis in Ref. 251 was part of the stabilizer-debottlenecking assignment. The conclusion reached was that when test data are simulated with too low a volatility the simulation compensates by using a greater number of stages (and, hence, higher efficiencies) to match the measured separation. In this case (e.g., the nC_4/C_5 pair in the stabilizer), the simulation will continue to give conservative predictions when extrapolated into different process conditions.

The converse occurs when test data are simulated with too high a relative volatility. The simulation compensates by using a smaller number of stages to match the measured separation. In this case (e.g., the C_3/iC_4 pair in the stabilizer), extrapolation to other process conditions will be optimistic, sometimes grossly so.

Based on the above, it was concluded that the simulation was a reliable basis for debottlenecking for the base case (similar feedstock to that used in one of the tests) and for alternative feedstocks that are not widely different from the base case. However, for those cases of feedstock variations where feed composition varied widely from the base case, the simulation could not be used with confidence until the inaccuracy in the C_3/iC_4 relative volatility was mitigated.

Postmortem The column was successfully debottlenecked. The same simulation (modified to account for the debottlenecking hardware modifications) was found to give superb predictions of the post-revamp performance.

CASE STUDY 1.13 LOCAL EQUILIBRIUM FOR CONDENSERS IN SERIES

Contributed by W. Randall Hollowell, CITGO, Lake Charles, Louisiana

This is my all-time favorite fractionation simulation problem. The entire refinery capacity was sometimes limited by the gas rate, which was calculated to be zero.

Installation An atmospheric crude distillation tower had an extremely broad boiling range overhead vapor with significant ethane, high propane, through full-range kerosene. There were three long, double split-flow condensers in series. The shells were flange to flange and located directly above the overhead accumulator.

Problem Simulation predicted a zero off-gas rate at peak summer temperatures. But actual off-gas rates were substantial, even in winter. Summer crude charge rate was sometimes reduced to avoid flaring of gas in excess of compressor capacity. There was a strong economic incentive to increase butane spiking of crude, but this was not done due to concerns that the gas rate would increase.

Component Balances Earlier calculations had failed to obtain an adequate material balance of the lightest components in the overhead. The naphtha GC analyses were found to be poor. Procedures were corrected by the laboratory, and good material balance closures were obtained.

Simulations predicted that all of the exiting vapor off gas should have been absorbed into the naphtha stream at the operating temperature and pressure. The naphtha had much lower light-ends concentrations than predicted: 30% of the predicted for propane, 50% for butanes, and 75% for pentanes concentration. These low concentrations in the naphtha provided the vapor off-gas flow.

With many sets of data, each giving good material balance closure, it was obvious that the vapor exiting the overhead accumulator was not in equilibrium with liquid exiting the accumulator. Condensers fouled severely on the tube side, but this did not explain the large deviations from equilibrium.

Theory Conventional process simulation assumes what can be called the "universal VLE model." This model assumes that VLE is universal, that is, holds at every location, between the total vapor flow and the total liquid flow. In shell-side condensation, the liquid and vapor are usually close to equilibrium locally when the liquid condenses on the tube surface. But after the liquid drops off the tube (and to the bottom of the shell), there is not enough vapor—liquid mixing to maintain equilibrium with the downstream vapor. Thus there is usually "local VLE" at the tube surface, but not universal VLE for the system. This local equilibrium is responsible for the phenomena of subcooled refluxes coexisting with uncondensed vapor. Condensers designed for total condensation have frequently been partial condensers because of local VLE.

Deviations from universal equilibrium can be large for condensers in series with broad boiling range mixtures. Deviations are particularly high for mixtures with high light-ends content and for arrangements where the liquid stays largely separated from the downstream vapor. This case study represents an extreme example of these deviations.

For the overhead accumulator, universal VLE requires that the operating pressure and the exiting liquid bubble point pressure be equal. But bubble point pressure was half of the operating pressure. If the entire exiting vapor flow had been absorbed into the naphtha stream, the bubble point pressure would still have been less than the operating pressure.

Solution A model was developed to more closely represent the condensation steps. Liquid condensed in each shell was assumed to be in equilibrium with the gas leaving that shell. After the liquid left the shell in which it condensed, it was assumed to have zero mass transfer with the gas phase but to be cooled to the local operating temperature. This model had only one-third of the total liquid (the one-third that condensed in the last shell) in equilibrium with the off gas. The other two-thirds of the liquid was much heavier and caused the overall liquid bubble point pressure to be about half that of the liquid that condensed in the last shell. The actual system was

more complex than the above model, in particular:

- The liquid condensed in each shell was heavier than the calculated liquid in equilibrium with the exiting vapor.
- Liquid condensed in an upstream shell experienced a moderate amount of mixing (and thus mass transfer) with downstream vapor.

The above two effects are in opposite directions and largely cancel each other for this case study (perhaps because of the double-split arrangement and three shells in series). This cancellation of errors caused the model to adequately match actual liquid composition and actual vapor rate leaving the overhead accumulator.

Morals For broad boiling range mixtures, condensers (particularly condensers in series) have less capacity than estimated by conventional simulation with universal VLE. This is a failure in simulation and design rather than an equipment failure.

A simulation based upon good operating data can often be used to adequately model the effect of local equilibrium. Good heat and material balances and confidence in them are necessary to step away from universal VLE assumptions and obtain realistic simulations.

Process designers have compensated for their lack of understanding by using large design margins for condensers, by specifying off-gas compressors for zero calculated gas rates, and by greatly oversizing off-gas compressors. These practices can still result in lack of capacity for installations such as in this case study. Even very rough estimates of local equilibrium effects can be far better than conventional calculations for series condensation.

For a single shell and moderate deviations from universal VLE, a reasonable subcooling delta temperature can sometimes be used for simulation and design. In extreme cases, calculations for zones in each shell may be necessary to give good simulation or design. For this case study, the zone method would probably have been required if the condenser paths had been many times longer than in a double split-flow configuration.

CASE STUDY 1.14 SIMULATOR HYDRAULIC PREDICTIONS: TO TRUST OR NOT TO TRUST?

Henry Z. Kister, reference 254. Reproduced with permission. Copyright © (1995) AIChE. All rights reserved

In this case study, a simulator hydraulic calculation led a plant to expect a capacity gain almost twice as high as the tower revamp actually achieved.

History A refinery vacuum tower was debottlenecked for a 30% capacity gain by replacing 2-in. Pall rings in the wash and heavy vacuum gas oil (HVGO) sections with 3-in. modern proprietary random packings. Only about 15–20% capacity gain was achieved. It was theorized that above this throughput vapor maldistribution set in

and caused the tower to lose separation. The refinery sought improvements to vapor distribution in an effort to gain the missing 10–15%.

Troubleshooting A vacuum manometer pressure survey showed that at the point where the tower lost separation the pressure drop was 0.65 in. H₂O/ft packing. Based on air/water measurements, many suppliers' packages take the capacity limit (or flood point) to occur at a pressure drop of 1.5–2 in. H₂O/ft packing. Work by Strigle (473), Rukovena and Koshy (418), and Kister and Gill (257, 259) demonstrated that such numbers are grossly optimistic for modern, high-capacity random and structured packings. Using published flood data, Kister and Gill (257, 259) showed that, for random and structured packings, the flood pressure drop is given by

$$\Delta P_{\text{flood}} = 0.115 F_{\text{P}}^{0.7} \tag{1}$$

where $\Delta P_{\rm flood}$ is the flood pressure drop (in. H₂O/ft packing) and $F_{\rm P}$ is the packing factor (ft⁻¹). This equation was shown to give a good fit to experimental data (many of which were generated by suppliers) and was later endorsed by Strigle (473) with a slight change of coefficient. For the high-capacity packing in the vacuum tower, the packing factor was 12. Equation 1 predicts that $\Delta P_{\rm flood}$ was 0.65 in. H₂O/ft packing, which coincided with the limit observed by the refinery.

For hydraulic calculations, gas velocity usually is expressed as a C-factor (C_S), (ft/s), given by

$$C_{\rm S} = U_{\rm S} \left(\frac{\rho_{\rm G}}{\rho_{\rm L} - \rho_{\rm G}} \right)^{0.5} \tag{2}$$

where U_S is the gas superficial velocity based on tower cross-sectional area (ft/s), ρ is the density (lb/ft³), and the subscripts G and L denote gas and liquid, respectively. The C-factor essentially is a density-corrected superficial velocity. The fundamental relevance of the C-factor is discussed elsewhere (251).

Based on a flood pressure drop of 0.65 in. H₂O/ft packing derived from Equation 1, the maximum efficient capacity of the new 3-in. random packing calculated by the Kister and Gill method (251) was at a C-factor of 0.38 ft/s. This is about 17% higher than the maximum efficient capacity for the previous 2-in. Pall rings, just as the refinery observed.

According to the supplier's published hand correlation, which we believe was similar to the one in the computer simulation, the maximum efficient capacity of the packing was at a C-factor of 0.43 ft/s, which is 13% higher than observed. This high C-factor matched a pressure drop of between 1 and 1.5 in. H₂O/ft packing, well above the value where the packing reached a capacity limit.

Epilogue Based on the hydraulic calculation in the computer simulation, the refinery expected that changing the 2-in. Pall rings to the 3-in. high-capacity random packing would increase capacity by 30%. In real life, just over half of the capacity increase materialized. The half that did not materialize is attributed to the optimistic prediction from the simulation.

CASE STUDY 1.15 PACKING HYDRAULIC PREDICTIONS: TO TRUST OR NOT TO TRUST

Background This case presents a number of experiences which were very similar to Case Study 1.14. In each one of these, vendor and simulator predictions for a packed tower were optimistic. In each one of these, the Kister and Gill equation (257, 259) gave excellent prediction for the maximum capacity. The Kister and Gill equation is

$$\Delta P_{\text{flood}} = 0.115 F_{\text{p}}^{0.7} \tag{1}$$

where ΔP_{flood} is the flood pressure drop (in. H₂O/ft packing) and F_P is the packing factor (ft⁻¹).

Tower A This was a chemical tower, equipped with wire-mesh structured packing with a packing factor of 21. The tower ran completely smoothly until reaching a pressure drop of 1 in. H_2O/ft packing, then would rapidly lose efficiency. This compares to a flood pressure drop of 0.97 in. H_2O/ft packing from Equation 1. Simulation prediction (both vendor and general options) predicted a much higher capacity.

Tower B This was a chemical tower equipped with random packing with a packing factor of 18. This column would rapidly lose efficiency when the pressure drop increased above 0.67 in. H₂O/ft packing. This compares to a flood pressure drop of 0.87 from Equation 1. The measurement was slightly lower than the prediction because the vapor load varied through the packings, so much of the bed operated at lower pressure drop. Simulation prediction (both vendor and general options) predicted a much higher capacity. Similar to Case Study 1.14, the plant initially theorized that the shortfall in capacity was due to vapor maldistribution.

Tower C This was a chemical absorber equipped with random packing with a packing factor of 18. The highest pressure drop at which operation was stable was 0.8 in. H₂O/ft packing. Above this, the pressure drop would rapidly rise. This compares to a flood pressure drop of 0.87 from Equation 1. Simulation predictions (both vendor and general options) were of a 20% higher capacity.

Tower D Random packing installed in a chemical tower fell short of achieving design capacity. The vendor method predicted flooding at a pressure drop of 1.5 in. H_2O/ft packing. With a packing factor of 18, Equation 1 predicted that the packing would flood much earlier at a pressure drop of 0.8 in. H_2O/ft packing. The packing flooded at exactly that pressure drop.

CASE STUDY 1.16 DO GOOD CORRELATIONS MAKE THE SIMULATION HYDRAULIC CALCULATIONS RELIABLE?

Henry Z. Kister, reference 254. Reproduced with permission. Copyright © (1995) AIChE. All rights reserved

What follows is an actual letter circulated by an engineer working for a reputable company. The names of the correlations cited, as well as a few sentences, were changed to protect those involved.

We have had a problem recently with the prediction of flooding in packed towers using the Smith correlation for packed tower capacity in the Evertrue Simulator. We used this for sizing a packed tower at 400 psia. The program predicted a percentage flood of 56 percent using the Smith correlation. The vendor predicted 106 percent of flood, and 123 percent of the packing useful capacity.

The Evertrue calculation is based on an article by Smith in Quality Chemical Engineering magazine. Smith's method, in turn, depends on an earlier correlation by Jones, also published in an article in Quality Chemical Engineering.

These correlations are neither well developed nor tested. Neither of these articles (Smith's and Jones') have undergone very close scrutiny, nor are the correlations from well-known textbooks or journals that have a tradition of peer review. One of the failings is the use of the correlation at high pressure with hydrocarbon systems. Smith's correction factor for high pressures produces numbers that are unreasonably high. There is no indication that this factor is supported either by correlation or by theory. In addition to the lack of credibility of Smith's values, the correlation of Jones, used as the basis of the Smith method, appears inaccurate for the high-pressure systems.

For these reasons, I would not recommend use of the Evertrue Smith correlation, regardless of the system pressure, for predicting whether or not a packed tower will work. Instead, the 1960 correlation included on Evertrue should be used. This correlation is based on well-known methods, and can be found in "Perry's Handbook." It predicts the tower would be at 96 percent of flood, compared to the 106 percent predicted by the vendor, which is much closer than the Smith correlation.

In either case, calculations must be verified by the packing vendor. I recommend that the vendor verifies the results even for estimates.

What Really Happened In our experience, both the Smith and the Jones correlations are excellent. The correlation that leaves a lot to be desired for modern packing calculations is the 1960 one. Nevertheless, the letter's author appeared to have reached the converse conclusion.

It is a sad fact of life that correlation authors always examine their correlations for good statistical fit but seldom properly explore and clearly define their correlation limitations. On page 39 of Ref. 259, Kister and Gill remark: "An excellent fit to experimental data is insufficient to render a packing pressure-drop correlation suitable for design. In addition, the correlation's limitations must be fully explored."

In contrast to the letter writer's comment, the problem is more acute in articles that are peer reviewed. These contain correlations based on fundamental models that are inherently complex. This complexity makes it very difficult to properly identify the limitations. A peer review offers little help unless the reviewer spends several days checking the calculations. This rarely happens.

The Smith correlation works very well for vacuum and atmospheric pressures, perhaps up to 50 psia. It was never intended to apply to 400 psia. Unfortunately, Smith's article only contained a hint of the pressure limitation but no firm statements to that effect. It, therefore, went into the Evertrue simulator without a warning flag

above 50 psia. In this case, the 1960 correlation was found to work well. This appears to be a case of two wrongs making a right.

Epilogue There are many correlations in the published and proprietary literature for which the limitations are neither well explored nor well defined. Limitations unflagged in the original articles remain unflagged in the simulator version.

Despite the letter writer's wrong conclusion, his bottom line is broadly valid. A simulator correlation cannot be trusted, even when the correlation is good, unless the correlation's limitations are known and included in the simulation. An independent verification, say, by a supplier or an independent method, is a good idea. When Distillation Design (251) was compiled, special effort was made to talk to authors of good correlations, with the objective of exploring their limitations and filling in the missing blanks. For instance, the pressure ranges for the application of Smith's correlation were listed in Distillation Design almost two years before the above letter was written.

Where Fractionation Goes Wrong

Fractioination issues featured very low on the distillation malfunctions list for the last half century (255). Only two issues rated a mention, intermediate-component accumulation and two liquid phases. Neither of these made it to the top 20 distillation malfunctions. This contrasts the author's experience. Intermediate-component accumulation is experienced frequently enough to justify a place in the top 20, maybe even close to the 10th spot. The large number of cases of intermediate-component accumulation reported in this book will testify to that. In many cases, the accumulation led to periodic flooding in the tower. Other problems induced by the accumulation include corrosion, product losses, product contamination, and inability to draw a product stream.

A second liquid phase, either present where undesirable or absent where desired, was troublesome in several case histories, most from chemical towers. In many cases, issues in the overhead decanter or its piping induced an undesirable phase either into the reflux or into the product. Presence or absence of a second liquid phase caused not only separation issues and production bottlenecks but in some cases also violent reactions, damage, and explosions.

Other fractionation issues include insufficient reflux, insufficient stages, insufficient stripping, and excessive bottom temperatures. Although basic to fractionation, it is amazing how often it is overlooked. Unique multicomponent issues include absorption effects in wide-boiling mixtures and location of side draws. Azeotropic and extractive distillation have their own unique challenges.

CASE STUDY 2.1 NO REFLUX, NO SEPARATION

Contributed by Ron F. Olsson, Celanese Corp.

The feed to a 55-tray tower came in 10 trays below the top. The tower was separating an alcohol as the distillate from a glycol as a bottom product. A simulation detected that the losses of glycol in the distillate were excessive. The glycol losses were

estimated to cost about \$250,000 per year. Further investigation revealed that the reflux had been eliminated. Apparently, the reflux rate was cut out during the 1970s, when energy savings were most important. Over the years, this mode of operation became the norm. Further, corrosion of the trays reduced their efficiency, causing the separation to deteriorate.

The glycol losses were drastically cut once the reflux was reintroduced.

CASE STUDY 2.2 HEAVIER FEEDSTOCK IMPEDES STRIPPING

Contributed by Dmitry Kiselev and Oleg Karpilovskiy, Koch-Glitsch, Moscow, Russia

Installation A diesel hydrotreating unit was revamped to a dewaxing process. Due to increase in production of wild naphtha and gases, the diesel stabilizer was revamped also. The revamp design proposed to use a fired heater reboiler to provide the desired diesel flash point. The refinery did not have enough time to revamp the heater, so the unit started with stripping steam injection under the bottom tray, instead of the heater reboiler circuit.

Problem After several months of operation, the refinery decided to complete the unit revamp. The heater reboiling circuit was made operational while the steam line was disconnected. The result was surprising: The flash point of diesel decreased by 20°C, even though design specifications of the reboiling circuit (flow rate and heater outlet temperature) were achieved.

Investigation The first suspicion was that tray damage occurred during start-up, but checking of this required a shutdown or gamma scans, which were expensive options in that location. A complete set of process data was collected instead and a tower simulation prepared. The feed composition was surprisingly much heavier than design. The ASTM D86 50% percent point increased from 265 to 320°C. The reflux rate was half the design value. The simulation showed almost no vapor in the stripping part of the column. The heater outlet temperature could not be increased beyond 330°C to generate additional vapor due to vibration of the 75-m-long heater outlet line. The simulation showed that heater outlet temperatures even as high as 350–360°C would have been insufficient for achieving the diesel flash point specification.

The reason for poor operation was the new feed composition. The reason for the heavier feedstock was a revamp of the atmospheric tower of the crude oil distillation unit that took place at the same time as the last stage of the revamp of the hydrotreating unit. The crude tower revamp added a diesel draw in order to send light diesel directly to product blending and to dewax the heavy diesel only.

Solution During the next turnaround, the stripping steam line was reconnected. Simultaneous use of stripping steam and reboiling allowed the tower to achieve the product specification.

CASE STUDY 2.3 POOR H₂S REMOVAL FROM NAPHTHA HYDROTREATER STRIPPER

Contributed by Mark Pilling, Sulzer Chemtech, Tulsa, Oklahoma

Installation Naphtha hydrotreater stripper, stripping H_2S from naphtha.

Problem Tower had been operating fine for extended period. At a later time, it could no longer meet H₂S specification for bottom product.

Troubleshooting The tower was operated at the same bottom temperature as it always had been, but the reflux rate was much lower than normal. Investigations revealed that the feed to the unit had become considerably heavier. For this heavier feed, the operating bottom temperature was too low to provide sufficient stripping for H_2S removal.

Solution Bottom operating temperature and reflux ratio were raised to ensure proper H_2S removal.

Morals Tower operation needs to vary to accommodate changing feedstocks. Operators need to be trained to recognize the critical operating set points.

CASE STUDY 2.4 HEAVIES ACCUMULATION INTERRUPTS BOIL-UP

Contributed by Ron F. Olsson, Celanese Corp.

Figure 2.1 shows a system that recovered product from residues. The system removed product continuously as an overhead product from column C1. The heavy residues were periodically removed from drum D1.

Occasionally, the temperature of drum D1 would rise to the point where the reboiler could no longer boil it. The plant would then dump the drum content out of the bottom (route B). When the drum contents were dumped, lots of lights were lost in the dump. When the reboil ceased, liquid from column C1 dumped and much of it ended in the D1 drum dump.

The problem was fixed by removing bottom residue streams continuously from both points A and B. It took some trial and error to correctly set the bottom rate.




Figure 2.1 System that recovers product from residue.

CASE STUDY 2.5 INTERREBOILER DRIVES TOWER TO A PINCH

Henry Z. Kister, references 254, 276. Reproduced with permission. Copyright © (1995) AIChE. All rights reserved

A composition pinch occurs when, due to an insufficient driving force, the change in composition on each successive distillation stage diminishes and approaches zero. In the stripping section, an insufficient driving force usually coincides with an excessively low stripping ratio (V/B). Increasing the stripping ratio can reinstate composition changes, but at the expense of higher vapor and liquid hydraulic load. These higher loads cannot be tolerated when the tower nears a capacity bottleneck.

In this case, a clever debottleneck scheme looked great on the simulation. Yet pinches and mislocated feeds, readily visible on McCabe—Thiele diagrams, remain hidden on computer screens. It took a McCabe—Thiele diagram (341, described in detail in Ref. 251) to see that the scheme would drive the tower too close to a pinch and would be risky. Fortunately, the McCabe—Thiele diagram was prepared before the scheme was implemented.

Background An olefins plant was being debottlenecked for a 15% increase in throughput. The C_2 splitter (Fig. 2.2a) was a major bottleneck. The tower contained 95 trays in the rectifying section and 45 trays in a smaller diameter stripping section. The vapor feed entered close to its dew point.




Figure 2.2 Proposed C₂ splitter debottleneck: (a) proposed changes, adding an interreboiler and splitting the feeds; (b) McCabe-Thiele diagram that clearly warned of imminent pinch. (From Ref. 254, 276. Reproduced with permission. Copyright © (1995) AIChE. All rights reserved.)

Hydraulic calculations showed that the rectifying section would be barely capable of handling the increased throughput. The stripping section was undersized for the higher throughput and would require an expensive retray with specialty high-capacity trays.

Alternative Scheme A clever alternative scheme was conceived with a potential of slashing the revamp costs as well as saving energy. There was scope to have the feed enter as two separate streams. One contained 70% ethylene, made up 60% of the feed, and was to enter on tray 55 (Fig. 2.2a). The second contained 50% ethylene, made up 40% of the feed, and was to enter on tray 45. To unload the bottom section, an interreboiler was to be added at tray 46, supplying about 10% of the total column heat duty. Since the interreboiler was to convert 10% of the liquid into vapor, the vapor and liquid traffic in the narrow-diameter section below would diminish by 10%. This unloading was enough to accommodate the post-debottleneck throughput.

In principle, the interreboiler was to unload the narrow-diameter section that bottlenecked the tower. Splitting the feed was to assist in expanding the stripping section from 45 to 55 trays without adversely affecting separation in the rectifying section. The extra stripping trays were needed to accommodate for the lower V/B (stripping ratio) generated below the interreboiler.

A computer simulation showed that the scheme would work well. There were no convergence problems, nor was there anything about the simulation that may indicate a potential problem. The scheme received the go-ahead.

Just prior to going into the final design, a McCabe-Thiele diagram was constructed to explore hidden traps (Fig. 2.2b). The pinch just below the interreboiler was glaring.

Postmortem The interreboiler caused the V/B for the section below to diminish almost to the minimum stripping. Although hydraulically the interreboiler would have fulfilled its function, the column may not have achieved the design separation due to the pinch. Alternatively, to overcome the pinch, the operator would have needed to raise both the reflux and reboil and would have possibly encountered a hydraulic bottleneck.

CASE STUDY 2.6 TEMPERATURE MULTIPLICITY IN MULTICOMPONENT DISTILLATION

Henry Z. Kister and Tom C. Hower, reference 263. Reproduced with permission. Copyright © (1987) AIChE. All rights reserved

Installation A lean-oil still in an absorption-refrigeration gas plant (Fig. 2.3a). This still was the last step of purification of the absorption oil before the oil was returned to the plant absorber to absorb heavy components from natural gas. Feed to the still was the absorption oil, containing the absorbed gasolines and some LPG. Lighter components were removed from the oil upstream of the still. Lean oil left




Figure 2.3 Multicomponent still that showed temperature multiciplity: (a) lean-oil still; (b) variation of lean-oil still top temperature with reflux. (From Ref. 263. Reproduced with permission. Copyright © (1987) AIChE. All rights reserved.)

as the still bottom product, while gasoline and LPG were the top product. The still operated at 210 psig. Note the large temperature difference between the bottom and top of the still.

The main objective of the still was to keep gasoline out of the column bottom. This was achieved by the furnace outlet temperature control. The reflux rate was trimmed by manually adjusting the flow controller set point, so as to give a reasonably constant column overhead temperature. The reflux drum was flooded, and liquid level in the condenser was used to control column pressure.

Problem The plant absorber appeared to be malfunctioning. It did not absorb all the heavy ends out of the gas.

Investigation The initial boiling point (IBP) of the lean oil leaving the still was low, which indicated the presence of a substantial quantity of gasoline in the still bottom. This suggested that the still was malfunctioning. The still showed no signs of flooding. The control temperature, the overhead temperature, and the reflux rate appeared to be at their design values. The composition of the top product was not analyzed.

Solution The problem was caused by insufficient reflux rate. The low reflux rate was unnoticed because of an incorrectly sized orifice plate in the still reflux line. When the orifice plate was replaced and the correct reflux flow set, the plant observed a large permanent increase in fuel usage and a large drop in the apparent quantity of absorption oil, indicating that the gasoline was being stripped off the bottom. Following this, the plant absorber started functioning normally and absorbing heavy ends out of the gas.

Analysis The problem was particularly difficult to detect because of the unusual behavior of the overhead and bottom temperatures. Normally, when a substantial amount of light impurity is present in the bottom, one would expect the bottom temperature to drop; when a substantial amount of heavy impurity is present in the column overhead, one would expect this temperature to rise. Over-reboiling can bring the bottom temperature back up, but in such a case, one would expect the top temperature to rise further above design.

The above considerations are generally valid for binary distillation and often, but not always, for multicomponent separations. This case is an example of a multicomponent distillation where the above considerations do not apply.

In general terms, at the low reflux rates the column was operated as a gasoline–LPG separator instead of an absorption oil–gasoline/LPG separator. This lowered temperatures throughout. However, the column was over-reboiled; this returned the bottom and top temperatures to their design values. This is explained in detail below.

At the low reflux ratio, a substantial fraction of the gasoline reached the bottom. This would have caused a lower temperature at the base of the column, but the control system increased the reboil rate (i.e., over-reboiled) to keep the bottom temperature up at design. Because of the low reflux ratio, however, the over-reboil action boiled over a significant fraction of absorption oil and perhaps most of the gasoline. The

column probably fractionated out most, but not all, of the absorption oil. The mixture arriving at the top tray therefore contained the LPGs, some gasoline, and a small quantity of absorption oil. The presence of the absorption oil acted to increase the top tray temperature; the absence of gasoline that was lost to the bottom acted to decrease it. By varying the reflux rate as in normal operation, one could keep the top temperature at its design value.

Variations of the column overhead temperature are shown in Figure 2.3b. Under all these conditions, bottom temperature was controlled at $525-550^{\circ}F$. The column overhead initially operated at point A at the low reflux conditions. At the correct reflux rate, the overhead temperature operated at point B. Note the existence of point C on this curve, at which an increase in reflux rate causes an increase in overhead temperature. This operating condition (point C) has actually been observed in this type of column.

CASE STUDY 2.7 COMPOSITION PROFILES ARE KEY TO MULTICOMPONENT DISTILLATION

Contributed by Frank Wetherill (retired), C. F. Braun, Inc., Alhambra, California

Installation A product column in a specialty chemical plant producing a heavy, water-soluble glycol product. The process is similar to that described in Case Study 15.1. The column separated glycol product from high-boiling residues. The column is shown in Figure 2.4a.

Problem Although water was removed from the column feed and water-forming reactions were suppressed by lowering the base temperature in a manner similar to that described in Case Study 15.1, a very small quantity of water (about 0.1%) was still present in the product. It was economical to remove even that amount of water from the product.

Investigation This amount of water was very small and could have originated either in the column feed or from water-forming condensation reactions at the column base. Tackling this problem at the source would have been difficult.

It was realized that the product was very hygroscopic. Therefore, it was suspected that after the product was condensed and subcooled in the overhead condenser it reabsorbed water from the inerts stream.

Solution It appeared beneficial to withdraw the product upstream of the point where it was being subcooled. A suitable point was the top tray of the column. The column was modified to withdraw product from this tray, as shown in Figure 2.4b. This eliminated the water problem.

Postmortem The relative volatility for glycol-water separation was large (the atmospheric boiling point of the glycol was greater than 400°F). Any liquid water present in the reflux stream therefore easily vaporized on the top tray.




Figure 2.4 Glycol product column: (a) initial; (b) modified.

It may appear that withdrawing water from the top tray, instead of from the reflux drum, would have enriched the product with the heavier impurity because the condenser stage was no longer available for the product-residue separation. This enrichment, however, was minimal, because even before the modification the condenser behaved as a total condenser from the product-residue separation viewpoint (product was withdrawn as liquid) and had therefore contributed little to the product-residue separation.

Another Plant A glycol/residue tower in a completely different plant and operated by a different company experienced a somewhat similar problem. In that case, the amount of water was small. Instead of escaping in the inerts route, the water was condensed and refluxed back into the tower. Over a period of time, water built up in the overhead loop and adversely affected product purity. The problem was solved by periodically running the reflux drum liquid to a flash tank.

CASE STUDY 2.8 COMPOSITION PROFILE PLOT TROUBLESHOOTS MULTICOMPONENT SEPARATION

Henry Z. Kister, Rusty Rhoad, and Kimberly A. Hoyt, references 254, 273. Reproduced with permission. Copyright © (1996) AIChE. All rights reserved

Engineers seldom bother plotting composition profiles in multicomponent distillation. Like the McCabe—Thiele and Hengstebeck diagrams, column composition profiles (generated from the compositions calculated by the simulation; Refs. 243 and 251 have detailed examples) are a superb analytical and troubleshooting tool that provides visualization that simulations do not. Undetected abnormalities often reveal themselves as a column malfunction after start-up. This case shows how a composition profile identified a very unforgiving column design.

Background A chemical vacuum tower containing structured packing (Fig. 24.1a and 2.5) separated a heavy key (HK) component from an intermediate key (IK) component in its lower section. There was a specification of 0.3% maximum IK in the bottom and 1.0% maximum HK in the vapor side product. Feed to the column contained many other components that were lighter or heavier than the keys.

Problem While the bottom product was on specification, the vapor side product contained about 10% HK, which was several times higher that the design.

Troubleshooting Initial suspicion was a malfunction of the structured packing or the distributors. The design height equivalent of a theoretical plate (HETP) was on the low side, but not grossly so. The lower bed was simulated by eight stages; six or seven would have been a closer estimate. The distributor design was found to be good, and the distributor was successfully water tested and debugged at the manufacturer's shop before being installed in the tower. The VLE data were examined. While not perfect, the volatility estimate was quite reasonable.




Figure 2.5 Composition profile pinpoints sensitivity of heavy key. (From Ref. 254, 273. Reproduced with permission. Copyright © (1996) AIChE. All rights reserved.)

Next, plugging of the packing or distributors was suspected. Extensive field tests, described in detail in Case Study 4.9, were performed and showed that the tower operated well below flood and that both the pressure drop and flood point were well inline with predictions. Gamma scans verified that distribution below the flood point was quite reasonable and there were no signs of plugging.

Likely Cause During the troubleshooting, the design simulation was revisited and the composition profiles plotted. The profiles plot the concentrations of each component in the liquid (one plot) and the vapor (a second plot) against the theoretical stage number. Figure 2.5 is a condensed version, singling out the IK in the liquid and the HK in the vapor. These were the prime actors in the current problem. The diagram shows an extremely steep peak for the HK in the vapor. Stage 18 vapor contains 55% HK. By the time the vapor draw-off is reached on stage 13 (five stages up), the HK concentration is supposed to drop to 1%. On stage 14, the HK concentration is about 7%, and on stage 15, it is 18%. Figure 2.5 therefore depicts a very unforgiving composition profile.

Achieving the design separation depends upon the lower packed bed successfully developing eight theoretical stages. Should this number fall a stage or two short, the concentration of HK in the vapor side draw would skyrocket, with product going severely off specification. Sources that can make the number of stages fall short of expectation by one or two were (and usually are) abundant. These include a slightly optimistic design HETP, inaccuracies in VLE, differences between design and actual feed compositions, relatively small scale fouling or maldistribution, and even disturbances to the feed and the heating and cooling media.

CASE STUDY 2.9 WATER ACCUMULATION CAUSES CORROSION IN CHLORINATED HYROCARBON TOWER

Installation A tower separating HCl and HC gases from chlorinated HCs (Fig. 2.6). There was a very small amount of water (\sim 3 ppm) in the feed.




Figure 2.6 Water accumulation in chlorinated hydrocarbon column.

Problem There was severe corrosion on trays 15–30. There was no corrosion at the top 5 trays and the bottom 15 trays. The column run length was less than a month; afterward it needed shutting down to replace the trays.

Cause Top temperature was too cold, and bottom temperature too hot, to allow water to escape. In the bottom section, repulsion of water by the chlorinated HCs increased its volatility. As a result, the water became trapped in the tower and concentrated near the feed. The accumulation could be predicted using a NRTL or UNIQAC model, but not using ideal solution or equation-of-state models.

Solution The problem was resolved by replacing trays 15–30 by trays fabricated from Hastelloy C.

Related Experience A decomposition reaction took place near the bottom of one chemical tower, yielding a corrosive compound. The boiling point of that compound was well below the tower overhead temperature. It therefore accumulated and corroded trays in the middle of the tower.

CASE STUDY 2.10 HICCUPS IN A REBOILED DEETHANIZER ABSORBER

Installation A refinery reboiled deethanizer absorber (Fig. 2.7). The top section of the tower used a naphtha stream to absorb C_3 and C_4 HCs from a gas stream that went to fuel gas.

Feed to the tower contained a small amount of water. Free water was removed in the feed drum upstream of the tower, but the separation was not perfect. In addition, the small quantity of water dissolved in the HC feed would not be removed in the feed drum.

Bottoms from the tower went to a debutanizer that operated much hotter than the deethanizer. The debutanizer recovered the C_3 and C_4 HCs in the top product, leaving gasoline as the bottom product.

Problem Plant economics favored maximizing recovery of C_3 and C_4 in the deeth-anizer bottoms. To achieve this, the control temperature in the stripping section was lowered. The system worked well for 2–3 days following the change. Then the debutanizer pressure suddenly shot up, and a large slug of water was observed to fill the boot of the debutanizer reflux drum. A few minutes later the water disappeared. Two to three days later the process repeated. The possibility of steam or water leaks was investigated, but none were found.

Solution The tower was returned to its previous mode of operation with the higher deethanizer control temperature.